N. U. COPTES HELL. J. 5			
DISTRIBUTION			
SANTA FE		17	
FILE		1	1
U.S.G.S.		Ī	
LAND OFFICE			
TRANSPORTER	OIL		
	GAS		
OPERATOR		3	
PRORATION OFFICE			
^			

NEW MEXICO OIL CONSERVATION COMM...ON

Form C-194

U.S.G.S. LAND OFFICE I RANSPORTER OIL GAS OPERATOR PRORATION OFFICE Operator ARMOGO, LTD. Address P.O. Box 20200, Dallas, Texas 75220 Reason(s) for filing (Check proper box) New Well Change in Transporter of: Recompletion Oil Ory Gas Change in Ownership Casinghead Gas Condensate	PECEIVED FOR 1 5 1971 FOR A CAL ACCUSANCE DE LA CERTICE	
I RANSPORTER GAS OPERATOR PRORATION OFFICE Operator ARWOOD, LTD. Address P.O. Box 20200, Dallas, Texas 75220 Reason(s) for filing (Check proper box) New Well Change in Transporter of: Recompletion Oil Dry Gas	FED 1 3 1971	
PRORATION OFFICE Operator ARWOOD, LTD. Address P. O. Box 20200, Dallas, Texas 75220 Reason(s) for filing (Check proper box) New Well Change in Transporter of: Recompletion Oil Dry Gas	1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 /	
ARWOOD, LTD. Address P.O. Box 20200, Dallas, Texas 75220 Reason(s) for filing (Check proper box) New Well Change in Transporter of: Recompletion Oil Dry Gas		
Reason(s) for f:ling (Check proper box) New We!1 Recompletion Oil Dry Gas Other (Please explain)	According to Environ	
New We!1 Change in Transporter of: Recompletion Oil Dry Gas Other (Please explain)		
New We!l Change in Transporter of: Recompletion Oil Dry Gas		
Obligation Containing		
If change of ownership give name and address of previous owner <u>Stallworth 911 5 Gas, 407 West Missouri Avenue, Midl</u>	and, Texas 79701	
II. DESCRIPTION OF WELL AND LEASE	Lease No.	
Rotary State 8 Artesia Feel State, Federal or Fee		
Location	_	
20 100	East	
Line of Section 40 Township 185 Range 28E , NMPM, Eddy	County	
III. DESIGNATION OF TRANSPORTER OF OIL AND NATURAL GAS Name of Authorized Transporter of Oil	y of this form in to be care!	
Injection Well	of this form is to be sent;	
Name of Authorized Transporter of Casinghead Gas or Dry Gas Address (Give address to which approved copy	of this form is to be sent)	
If well produces oil or liquids, quive location of tanks. Unit Sec. Twp. Rge. Is gas actually connected? When give location of tanks.	Is gas actually connected? When	
If this production is commingled with that from any other lease or pool, give commingling order number: IV. COMPLETION DATA		
Designate Type of Completion — (X) Oil Well Gas Well New Well Workover Deepen Plug E	Back Same Res'v. Diff. Res'v	
Date Spudded Date Compl. Ready to Prod. Total Depth P.B.T	·.D.	
Elevations (DF, RKB, RT, GR, etc.) Name of Producing Formation Top Oil/Gas Pay Tubine	g Depth	
Perforations • Depth	Casing Shoe	
TURING CASING AND CEMENTING RECORD		
TUBING, CASING, AND CEMENTING RECORD HOLE SIZE CASING & TUBING SIZE DEPTH SET	SACKS CEMENT	
V. TEST DATA AND REQUEST FOR ALLOWABLE (Test must be after recovery of total volume of load oil and must	t be equal to or exceed top allow	
OII. WELL Date First New Oil Run To Tanks Date of Test Producing Method (Flow, pump, gas lift, etc.)		
Length of Test Tubing Pressure Casing Pressure Chake	, Size	
Actual Prod. During Test Oil-Bbls. Water-Bbls. Gas-M		
GAS WELL		
	ty of Condensate	
Testing Method (pitot, back pr.) Tubing Pressure (Shut-in) Casing Pressure (Shut-in) Choke	Size	
VI. CERTIFICATE OF COMPLIANCE OIL CONSERVATION	COMMISSION	
APPROVED MAR 4 1971	, 19	
I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given above is true and complete to the best of my knowledge and belief. BY	1 / / / / / / / / / / / / / / / / / / /	
ARMOOD, LTD.		
	nce with RULE 1104.	
	r a newly drilled or deepened	
Frazier Armond (Signature) Con Bondard Well, this form must be accompanied by	= fendiation of fue dealettor	
Frazier Arwood (Signature) Gen. Partner well, this form must be accompanied by tests taken on the well in accordance well sections of this form must be fit	with RULE 111.	
Frazier Arwood (Signature) Gen. Partner (Title) Feb. 1, 1971 If this is a request for allowable for well, this form must be accompanied by tests taken on the well in accordance well able on new and recompleted wells. Fill out only Sections I. II. III. a	with RULE 111. Hed out completely for allow	