

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

NOV 21 1980

O. C. D.
ARTERIA OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. NM 647	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
<p>1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WATER INJECTION WELL</p>		7. Unit Agreement Name
<p>2. Name of Operator BOYD OPERATING COMPANY</p>		8. Farm or Lease Name ROTARY STATE
<p>3. Address of Operator P. O. Box 1756, Roswell, New Mexico 88201</p>		9. Well No. 8
<p>4. Location of Well UNIT LETTER J 2650' FEET FROM THE N LINE AND 1330 FEET FROM THE E LINE, SECTION 20 TOWNSHIP 18S RANGE 28E NMPM.</p>		10. Field and Pool, or Wildcat Art. Qn. Gbg S.A.
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3596 G.L.</p>		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/6/80 Rigged up service unit to P&A. Pulled 2 Jts. Packer hung. Ran swab to check depth. Swab would not come back into tubing (plastic tubing).

10/7/80 Cut sand line. Circulated packer up hole 4 jts.

10/8/80 Cut tubing 8' above packer. Pulled 60 jts. of 2 7/8".

10/9/80 Rigged up reverse unit. Picked up 2 7/8" and 1 joint of wash pipe. Circulated to top of fish.

10/10/80 Ran overshot and jarred packer loose. Pulled fish out. Ran in with wire shoe to recover wire line cutting tools and swab. No recovery.

10/13/80 Prepared to cut casing. Picked up and casing parted. Pulled 15 jts of 4 1/2" casing.

10/14/80 Ran 2 7/8" tubing and worked into 4 1/2" csg. Ran thru-tubing gun and perforated 3 holes at 1300', 900', and 600'. Ran 4 1/2" retainer and set at 1950'. Squeezed 50 sacks into perforations (1200 psi).

10/15/80 Tag cement at 1480'. Pumped 60 sack plug at 1308'. Tag cement at 540'. Spot 70 sx plug over stub of 4 1/2" casing @ 528'. Circulated to surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J M Boyd TITLE Operator DATE 11/20/80

APPROVED BY Mike S. Tuttlefield TITLE OIL AND GAS INSPECTOR DATE FEB 02 1981

CONDITIONS OF APPROVAL, IF ANY: