

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

SEP 28 1973

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG-2000
7. Unit Agreement Name
8. Farm or Lease Name Anderson State
9. Well No. 1-Y
10. Field and Pool, or Wildcat Wildcat
12. County Eddy

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER-  
2. Name of Operator  
Charles B. Read  
3. Address of Operator  
P. O. Box 2126, Roswell, New Mexico 88201  
4. Location of Well  
UNIT LETTER G, 1980 FEET FROM THE North LINE AND 1800 FEET FROM  
THE East LINE, SECTION 14 TOWNSHIP 18-S RANGE 24-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3686 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug well as follows:

Cut 4 1/2" casing at approximately 5990' and pull.  
Fill hole with good mud.  
Set cement plug over perfs. 6351-6388'. 255X  
Set 35 sack cement plug at 4 1/2" casing stub.  
Set cement plug 3900-4000'. 35 SX  
Set cement plug 2700-2800'. 35 SX  
Set cement plug in bas of 8 5/8" casing, 1500-1600'. 35 SX  
Set surface plug.  
Install regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Carl A. Schellinger TITLE Agent DATE 9/26/73

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE OCT 1 1973

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness

\* as noted above Plugging