

Form 9-321
(May 1968)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN PLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 025503

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Ginsberg-Federal

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Shugart

11. SEC. T. R. S. M. OR BLK. AND
SURVEY OR AREA

Sec. 25-18S-30E

12. COUNTY OR PARISH

Eddy

13. STATE

N. Mex.

SUNDY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Hanson Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 1515, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface1650 FNL & FEL
Sec. 25, T-18-S., R-30-E.
Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, ST, GR, etc.)

3560 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*7-29-69 Perf. 1 - 0.45" jet per foot at 3344', 3346', 3352', 3398', 3400', 3402',
3404', 3528', 3530', 3532', 3610', 3612', 3614', and 3616'. Ran 3 1/2",
N-80 tubing with HOWCO HM straddle packers set at 3520' and 3495'.7-30-69 Frac. each zone (3344 - 3404' & 3528 - 3616') limited entry with 500 gals.
DS-30 acid + 15,000 gals. lease oil + 14,000 lbs. 20-40 sand + 1000 lbs. 10-20
sand. Zone 3528 - 3616' treated 20.6 BPM @ 5000#, ISDP 1250#. Zone
3344 - 3404' treated 19.9 BPM @ 5200#. ISDP 2150#.RECEIVED
AUG 11 1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Manager

DATE

8-8-69

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

AUG 11 1969

CONDITIONS OF APPROVAL, IF ANY: