STATE OF NEW MEXICO		
ENERGY AND MINERALS DEPARTME		
we. of conice acceived 2	OIL CONSERVATION DEVISION	
DISTRIBUTION	P. O. BOX 2083	Form C-103
SANTA FE	SANTA FE, NEW MEXICO 87501	Revised 10-1-78
PILE 1	NOV 1 0 1980	Sa. Indicate Type of Lease
U.S.O.S.	1 NOV 1 0 1980	
LAND OFFICE		State Foe XX
ОРЕЛАТОЛ	J O. C. D.	5. State OII & Gas Lease No.
	ARTESIA, OFFICE	
LOO NOT USE THIS FORM FOR PAC USE "APPLICAT	AND TICES AND REPORTS ON WELLS prosals to prill on to decert or plug back to a different reservoir. Ion for Permit - " (Form C-101) for such proposals.)	
1.		7. Unit Agreement Name
	OTHER-	
2. Name of Operator		8. Farm or Leuse Name
DAVID FASKEN 🗸		Brown-Yates Com.
J. Address of Operator		9. Well No.
608 First National Bank Building, Midland, Texas 79701		1
S. Location of Well	ink burrunig, mutanu, rexas 73/01	
	000 East 1050	10. Field and Pool, or Wildcat
UNIT LETTER	990 East Line AND 1650 FEET FR	West Atoka Morrow Gas
		711111111111111111
THE South LINE, SECTION	ON 24 18-S NANGE 25-E NM	
	•	
() 15. Elevation (Show whether DF, RT, GR, etc.)		12. County
	3451' GR	Eddy
Check	Appropriate Box To Indicate Nature of Notice, Report or (Other Data
		NT REPORT OF:
	30832002	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TINPONANILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL ON ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
17. Describe Proposed or Completed Op work) SEE RULE 1103.	perations (Clearly state all pertinent details, and give pertinent dates, includ	ing estimated date of starting any proposed

- 10-18-80 MI & RU DA&S Oilwell Servicing Co., Inc. plugging unit & equipment. (Please refer to attached report).
- 11-1-80 Location cleaned up & leveled well plugged & abandoned. Well bore from surface down to 2840' released to Yates Petroleum Corp.

Dosted ID-2 Dosted ID-2 Dest (Deriver 80 Dest (Deriver 80

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Robert H. Angevine, Agent 10-29-80 NUV 1 3 1980 SUPERVISOR, DISTRICT II

CONDITIONS OF APPROVAL, IF ANY

Brown-Yates #1

<u>8-28-80---RU Mack Chase swab unit, O# tbg pressure, 70 psig csg pressure, static FL @ 700' from surface, swabbed fluid down to 5400', recovered gray to black muddy water - apparently csg & tbg leak. RD swab unit, well SI.</u>

 $\frac{8-29-80}{1}$ ---Well SI - waiting for A.F.E. to plug & abandon. Dropping from report until plugging operations commence.

<u>10-18-80---MI & RU DA&S well plugging unit & equipment, removed Christmas tree, installed BOP's, attempts to unseat Otis P.L. pkr @ 8873' were unsuccessful.</u> 2-3/8" tbg stretch measurements indicate tbg is stuck @ 6393'. SDON.

<u>10-19-80</u>---RIW w/1-7/16" collar locator on electric line, found 18" of tbg movement @ 7037', 6" of tbg movement @ 7510', & no tbg movement @ 7763'. RU DA&S pump, could not pump down 2-3/8" tbg @ 2000 psig. RU Halliburton & pumped down 2-3/8" tbg w/formation water & circulated out 2-3/8" x $4\frac{1}{2}$ " annulus w/13 bbls "in" - 1/2 BPM @ 2450 psig, 3/4 BPM @ 3250 psig, 1-1/2 BPM @ 3000 psig down to 2750 psig. Pumped a total of 50 bbls. SDON.

10-20-80---SD for Sunday.

<u>10-21-80---</u>Pumped 218 bbls fresh water down tbg. Circulated out 2-3/8" x $4\frac{1}{2}$ " annulus, $\frac{1}{4}$ BPM @ 2200#. Picked up on tbg, stretch measurement indicates tbg still stuck @ 7400'. Ran in tbg w/jet cutter & cut tbg @ 8724' KB. Worked tbg between 30,000# & 65,000# & gradually worked 10' sub & 2 jts out of hole. RU pump truck, circulated 20 BW down tbg, $\frac{1}{2}$ BPM @ 200#. Mixed 35 sx Class "C" cement w/bottom of tbg @ 8714'. Pulled 20 stands tbg & SDON.

<u>10-22-80---RIW w/2-3/8</u>" tbg & tagged top of cement plug @ 8170' (35 sx cement plug from 8714' up to 8170'). POW w/2-3/8" N-80 4.70# EUE 8rd thd tbg, stripped wellhead, set in hydraulic jacks & welded $4\frac{1}{2}$ " lift nipple to $4\frac{1}{2}$ " csg - stretch measurements indicate csg free to 4826'. SDON.

<u>10-23-80---RIW</u> w/jet cutter & cut $4\frac{1}{2}$ " csg @ 5025', pulled & recovered 56 jts $4\frac{1}{2}$ " csg (approximately 5020'). SDON.

10-24-80---Set 35 sx-cement plug across csg-stub @ 5020', SD - WOC.

<u>10-24-80---CORRECTED REPORT</u>: Set 50 sx Class "C" cement plug across $4\frac{1}{2}$ " csg stub @ 5050'. SD - WOC.

10-25-80---RIW w/tbg & tagged cement @ 5000', only realized 50' of fill from 50 sx cement. Mixed another 50 sx Class "C" cement w/bottom of tbg @ 5000', displaced w/S.W. mud. Pulled 25 stands tbg & SDON.

10-26-80---RIW w/tbg & tagged top of cement @ 4832' for 168' of fill. Set plug #4 from 4350' up to 4233' w/35 sx Class "C" cement, and plug #5 from 3000' up to 2840' w/50 sx Class "C" cement. RD csg pulling & plugging tools.

10-27-80---SD for Sunday.

10-28-80---WOC & moving out csg plugging equipment. Well plugged & abandoned.