

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM-025503

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry Hole		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Hanson Oil Corporation		8. FARM OR LEASE NAME Ginsberg Federal	
3. ADDRESS OF OPERATOR P. O. Box 1515 - Roswell, New Mexico 88201		9. WELL NO. 5	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FSL & 1650' FEL Sec. 24, T-18-S, R-30-E, NMPM Eddy County, New Mexico		10. FIELD AND POOL, OR WILDCAT Shugart	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 24, T-18S, R-30E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3612.4 GL 3614.4 DF		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

As verbally by Mr. Knauf, U.S.G.S., Artesia, it is proposed to plug and abandon the referenced well as follows:

20 sx. @ 3650-3744'

20 sx. @ 3350-3450'

35 sx. @ 1725-1825' (100' plug across 5½" casing stub)

10 sx. @ 0-75'

All plugs are to be set in heavy mud. Location will be cleaned up and a regulation marker set.

RECEIVED

JAN 12 1972

O. C. C.
ARTESIA, OFFICE

RECEIVED

JAN 11 1972

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Gerald E. Harrington

TITLE

Geologist

DATE 1-10-72

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JAN 11 1972

R. L. BECKMAN

ACTING DISTRICT ENGINEER

Subject to placing 120' cont plug
top salt, which would be in & out
of 8½" Cog shoe.

*See Instructions on Reverse Side