	N. M. O. C.	C CORY -		with it
rm 9-331	L TED STATES	SUBMIT IN TR. CAT		d. (197)2 u No. 42-R1424.
	MENT OF THE INTERI	OR (Other instructions on a verse side)	5. LEASE DESIGNATION	
GEOLOGICAL SURVEY			NM-025503	
	ICES AND REPORTS C		6. IF INDIAN, ALLOTTEE	OR TRIBE NAME
(Do not use this form for propo	sals to drill or to deepen or plug b ATION FOR PERMIT—" for such pr	ack to a different refer ofr.	~	
	ATION FOR PERMIT—" for such pr		7. UNIT AGREEMENT NAM	M 10
OIL GAS OTHER	Dry Hole	12 7 1070		
WELL WELL OTHER	DIY HOLE		8. FARM OR LEASE NAM	E
Hanson Oil Corpora	ation /	<u>C. C. p</u>	Ginsberg	Federal
ADDRESS OF OPERATOR		ARTESIA, OFFICE	9. WELL NO.	
P. O. Box 1515 - R LOCATION OF WELL (Report location of	Coswell, New Mexic	to 88201	10. FIELD AND POOL, OB	WILDCAT
See also snace 17 below.)	FEL & 1650' FSL		Shugart	
	24, T-18-S, R-30-	E	11. SEC., T., B., M., OR BI SURVEY OR ARBA	LK. AND
	County, New Mexic			
Eddy	-		Sec. 24, T-	
4. PERMIT NO.	15. ELEVATIONS (Show whether DF,		12. COUNTY OR PARISH	
	3631.8 GL 364	1.8 KB	Eddy	<u>New Mexi</u> co
Check A	ppropriate Box To Indicate N	lature of Notice, Report, or	r Other Data	
NOTICE OF INTER	EQUENT REPORT OF:			
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	
	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	81NG
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMEN	τ* <u>X</u>
REPAIR WELL	CHANGE PLANS	(Other)	its of multiple completion	on Well
(Other) 7. DESCRIBE PROPOSED OR COMPLETED OF	PERATIONS (Clearly state all pertinen ionally drilled, give subsurface local	Completion or Reco	mpletion Report and Log for	m.)
35 sx. plug @ 3950 40 sx. plug @ 3360 35 sx. plug @ 1750 35 sx. plug @ 750- 10 sx. plug @ 0-37 All plugs were set set. The location	0-3500' 0-1850' -850' 7'	d up and is read	ry hole marker y for inspecti	on.
		J.	NERCE STREET	
			ATTER	
8. I hereby certify that the foregoing		Geologist	DATE12-	
SIGNED AMAIN C.				
SIGNED Anald E.				
SIGNED ANALO E				
	ffice use)			

.

ı.