ETEIVED

| NO. OF COPIES RECEIVED | DEC 1 9 1972 NEW MEXICO OIL CONSE D. C. C. ARTESIAOCO FICARTESIA 1 - FILE | DEC 1 3 1972 D. C. C. Artegia, office | Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Inalcate Type of Lease State XX Tee 5. State Oll & Gas Leage No. B-1565 |
|-----------------------------|--|--|---|
| OIL GAS WELL | RY NOTICES AND REPORTS ON W DPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC ION FOR PERMIT - (FORM C-101) FOR SUCH | ELLS R TO A DIFFERENT RESERVOIR. PROPOSALS.) | 7. Unit Agreement Name |
| | BS, NEW MEXICO 88240 | | 8. Farm or Lease Nume STATE "BJ" 9. Well No. 1 |
| | FEET FROM THE | | |
| | 36 TOWNSHIP 13 13 15. Elevation (Show whether DF 3538 GL | | 12. County EDDY |
| 16. Check A NOTICE OF IN | Appropriate Box To Indicate Nat ITENTION TO: | | report of: |
| PERFORM REMEDIAL WORK | | REMEDIAL WORK XX | ALTERING CASING |

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled rods and tubing. Set cast iron bridge plug at 3260!. Dumped 1-1/4 sacks cement on top. PBTD @ 3250'. Set retrievable bridge plug @ 2716'. Tested casing with 3000# ,OK. Spotted 500 gals. 15% NE Acid. Perforated casing from 2512-20' with 16 jet shots. Fraced down casing with 60,000 gals. gelled water and 75,000# of 20-40 sand and 15,000# 10-20 sand. Maximum pressure 2650#, minimum 2500#. ISIP 1800#, 15 minute shut in pressure 1500#. Average rate 35 BPM. 18-1/2 hour SIP 500#. Bled back estimated 70 BLW. Washed off 18' of sand and reset bridge plug @ 2463'. Tested with 3000#, OK. Spotted 500 gals. 15% NE Acid. Perforated casing from 2402-06' with 16 jet shots. Treated with 30,000 gals. gelled water and 37,500# of 20-40 sand and 7,500# of 10-20 sand. Maximum pressure 3400#, minimum 2600#, ISIP 1850#. 15 min. SIP 1500#. Average rate 32 BPM. 17-1/2 hr. SIP 500#. Bled back estimated 170 BLW. Washed 15' sand off BP; recovered BP and pulled. Ran tubing and set at 3232'. Ran rods and put on pump. (The 3295-3605' perforations were abandoned since isolation tests with a packer showed it bo be producing only 4-5 BO and all the water. The perforations 3187-99' were producing no water and most of the oil.) Total production prior to remedial work was 12 BO and 50 BWPD; on 24 hr. test ending 12-15-72, well pumped 51 BO and 21 BLW. Still need to recover 1687 BLW.

| 18. I hereny certify that the information above is true and comple | ete to the best of my knowledge and belief. | ····· |
|--|---|-----------------|
| SIGNED | AREA SUPERINTENDENT | DATE 12-11-72 |
| www. W.a. Greesett | TITLE OIL AND GAS INSPECTOR | DATE DEC 2 1972 |

WLG/bh