

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
	1
	1
	1
	1
	1
	1
	1
	1

NEW MEXICO OIL CONSERVATION COMMISSION
3-NMOCC
1-File

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-68

5a. Indicate Type of Case
 State ☒ Fee ☐
 5. State Oil & Gas Lease No.
B-1565

SUNDRY NOTICES AND REPORTS ON WELLS
 (7) USE THIS FORM FOR PROPOSALS TO CEMENT OR TO DEEPEN OR PLUG A WELL TO NO DEEPER THAN 100 FEET FROM THE SURFACE.
 USE "APPLICATION FOR PERMIT TO CEMENT OR TO DEEPEN OR TO PLUG A WELL" (FORM C-101) FOR SUCH PROPOSALS.

RECEIVED

☒ GAS
☐ WELL
☐ OTHER

AUG 13 1975

GETTY OIL COMPANY

P.O. BOX 249, HOBBS, NEW MEXICO 88240

O. C. C.
ARTESIA, OFFICE

7. Unit Agreement
 8. Farm or Lease No.
STATE "BJ"
 9. Well No.
2
 10. Field and/or Wildcat
YATES 7 RIVERS
 12. County
EDDY

4. Location of Well
 C 660 NORTH 1980
 WEST 36 18-S 30-E
 LINE, SECTION TOWNSHIP RANGE NEPRA.

11. Elevation (Show whether DF, RT, GR, etc.)
3534 D.F.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO
 SUBSEQUENT REPORT OF

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTER OR CHANGE ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
 PULL OR ALTER CASING ☐ OTHER ☐ CASING TEST AND CEMENT JOB ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated completion date). SEE RULE 1103.

1. Set CIBP @ 2300' and dump 35' cement on top.
2. Fill hole with/9.5# Brine mixed with 25 sks. per 100 Bbl. Salt Gel.
3. Place 100' Cement Plug with top @ 700'.
4. Place 10 sk. Plug @ Surface.
5. Set P/A Marker and Clean off location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.
 Original Signed By
 SIGNED **C.L. Wade: O. L. WADE** TITLE **AREA SUPERINTENDENT** DATE **AUGUST 11, 1975**

APPROVED BY **W. A. Gussert** TITLE **SUPERVISOR, DISTRICT #** DATE **AUG 13 1975**

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness
Plugging