Important RECEIVED Proc100 at the second of the sec	NEW MEXICO OIL CONSERVATION COMMISSION		·		
The UTION NEW MEXICO OIL CONSERVATION COUNTSION C.00 act C.000 ALE Interview Count FEB 1: 1975 ALE D.C.C. D.C.C. AND OFFICE D.C.C. STREET AND COUNTSION Stand Office D.C.C. Street And Count Stand Office Dry Hole Free And Count The Office Petroloun Count of Street And Count Yates Petroloun Corportion And Office Yates Petroloun Corportion Prevent And Count Yates Petroloun Corport Not Betroit And Count Yates Petroloun Corport Street And Count Yates Petroloun Corport Not Betroit And Count Yates Petroloun	Image: International mean data in the WHENCO OIL CONSERVATION COMMISSION C.C.C. E.	. L COPIES RECEIVED		OFFIVE	Form C-103
Add FEB 1: 1975 Social D. C. C. And OFFICE D. C. C. Deriver of the formation of the control of the	Act FEB 11 1975 So.d. D.C.C. Act D.C.C. <td>TRIBUTION</td> <td></td> <td></td> <td></td>	TRIBUTION			
A.G	Add. Add. Add. Add. Bate Office The Office	FE	NEW MEXICO OIL	CONSERVATION COMMISSION	Effective 1-1-65
3.3.3. D. C. C. ARTESIA. OFFICE Source DI & Gonz Cases Non- Penaros Pres Source DI & Gonz Cases Non- Penaros Source DI & Gonz Cases Non- Penaros Pres Source DI & Gonz Cases Non- Penaros Source DI & Component Non- Penaros Mine Di Component Non- Penaros Dry Hole 7. Cunt Aprica Non- Penaros Source Di A data Source Non- Penaros Mine Di Component Non- Penaros Dry Hole 7. Cunt Aprica Non- Penaros Source Di A data Source Non- Penaros Mine Di Component Non- Penaros Dry Hole 7. Cunt Aprica Non- Penaros Source Di A data Source Di Non- Penaros Mine Di Component Non- Penaros Di Component Non- Penaros Source Di Non- Penaros Source Di Non- Penaros 25 romenaro Source Di Non- Penaros Source Di Non- Penaros Di Component Non- Penaros Source Di Non- Penaros 25 romenaro Source Di Non- Penaros Source Di Non- Penaros Di Component Non- Penaros Source Di Non- Penaros 25 romenaro Source Di Non- Penaros Source Di Non- Penaros Source Di Non- Penaros Source Di Non- Penaros Source Di Non- Penaros 26 romenaros Source Di Non- Penaros Acterno Component OF Source Di Non- Penaros 27 romenaros Source Di Non- Penaros Acterno Component OF<	3.3.5. D. C. C. Store Of a Gallesse ber set of rank of the set of a Gallesse ber Store Of a Gallesse ber set of rank of the set of a Gallesse ber Store Of a Gallesse ber set of rank of the set of a Gallesse ber Store Of a Gallesse ber set of rank of the set of a Gallesse ber Store Of a Gallesse ber set of rank of the set of a Gallesse ber Store Of a Gallesse ber set of rank of the set of a Gallesse ber Store Of a Gallesse ber set of rank of the set of a Gallesse ber Store Of a Gallesse ber set of rank of the set of a Gallesse ber Store Of a Gallesse ber set of the set of a Gallesse ber Dry Blode Store Of a Gallesse ber 207 Gouth 4th Street - Artesia, NM 88210 Store of a Gallesse ber Store of a Gallesse ber 207 Gouth 4th Street - Artesia, NM 88210 Store of a Gallesse ber Store of a Gallesse ber 207 Gouth 4th Street - Artesia, Store of Store to Gallesse ber Store of a Gallesse ber Store of a Gallesse ber 207 Gouth 4th Street - Artesia, Store of Store to Gallesse ber Store of a Gallesse ber Store of a Gallesse ber 207 Gouth 4th Street - Artesia, Store of Store to Gallesse ber Morth Store of a Gallesse ber 208 Gouth 4th Street - Artesia, Mathe Store of Gallesse	1LE		FEB 1 1 1975	For Industry Theory of Lague
AND OF THEE C. C. C. DEFATOR SUMDEY NOTICES AND REPORTS ON WELLS Deside of a deside the control of the deside of the deside the deside the deside the deside the deside the deside of the deside the	AND OFFICE Cl. C. C. BERATOR SUNDRY NOTICES AND REPORTS ON WELLS. Be abover rearrent intervention of the second and t	.5.G.5.			
Perator	SUNDER NOTICES AND REPORTS ON WELLS. use with use transformed transformed to the transformed transformed transformed to the transformed transformed to the tr	AND OFFICE		0 C C	
SUNDRY NOTICES AND REPORTS ON WELLS. Base of the formation of the second of t	SUNDRY NOTICES AND REPORTS ON WELLS. With the activation of the second structure according according to the second structure according to the sec	PERATOR			5. State Off & Gas Lease No.
. Dry Hole 7. Cen approximate hands Name of Counteer *********************************	With		· · · · · · · · · · · · · · · · · · ·		
State of Consider Dry Hole I. Fam of Loads Have Name of Consider Nine ald "B1" Com Nine ald "B1" Com Address of Consider 207 South 4th Street - Artesia, NM 88210 I. Felder ad Feel of Culled December at Wolf 200 etce 12. Felder ad Feel of Culled Inc. East	Base of Operation Dry Hole I. Frame of Loade Hase Name of Operation Ainca id "D1" Com Address of Operation S. Well D2. 207 South 4th Street - Artesia, NM 88210 S. Well D2. Lectures al Vector 200 Inc. alco 1 Well 200 Lectures al Vector 200 Inc. street A 600 Inc. street A 610 Inc. street A 620 Inc. street	SUNDR DO NOT USE THIS FORM FOR PROF USE "APPLICATION	NOTICES AND REPORT	S ON WELLS plug back to a different reservoir. or such proposals.)	7. Unit Agreement Name
With Dome of Dependence Note: No	With			Dry Hole	
Yates Petroleum Corporation Rincald "E" Com Address of General 207 South 4th Street - Artesia, N1 88210 N. Well No. 12000000000000000000000000000000000000	Yates Petroleum Corporation Rincald "27" Com Address of Genetics 207 South 4th Street - Artesia, Ki 88210 K. Well Me. 207 South 4th Street - Artesia, Ki 88210 K. Well Me. 10 1000 Morth List Am 620 11 1000 1000 Morth List Am 620 11 11 12 County 12 12 County 12 County 12 13 1460 Morth List Am 620 Hereine 14 County 12 County 12 14 County 12 County 12 County 14 County 12 County 12 County 15 County 14 County 12 County 16 County 12 County 12 County 17 County 12 County 12 County 18 County County County 12 County 14 County County County County County County	WELL WELL	OTHER-		8. Farm or Lease Name
Arters of Conductor 207 South 4th Street - Artesia, N1 88210 average average average 207 South 4th Street - Artesia, N1 88210 average average average average 207 South 4th Street - Artesia, N1 88210 average average average average 207 South 4th Street - Artesia, N1 88210 average average average average 208 average 209 average average average average 208 average 25 remerge average average average 208 average 25 remerge average average average 208 average 25 remerge average average average 200 average 25 remerge average average average 200 average 25 remerge average average average 201 average 25 remerge average average average 201 average 25 remerge average average average 201 average 25 remerge average	Attess Petroledin COLDURICOLOUR COLDUCT 207 South 4th Street - Artesia, Nil 88210 Leaders of Count 4th Street - Artesia, Nil 88210 Leaders of Count 4th Street - Artesia, Nil 88210 Leaders of Count 4th Street - Artesia, Nil 88210 Leaders of Count 4th Street - Artesia, Nil 88210 Leaders of Count 4th Street - Artesia, Nil 88210 Leaders of Count 4th Street - Artesia, Nil 88210 The East the scenes 25 Leader 4th Street - Artesia, Nil 88210 Lis Count 4th Street - Artesia, Nil 88210 Check Appropriate Barts attree of Notice, Report of Other Data subscent 4th Street - Artesia Street -				Kincaid "BI" Com
207 South 4th Street - Artesia, N1 68210 III (2000) Local of Noil 1000 Vertice A 600 Vertice A 600 Vertice A 600 Vertice A 600 Vertice A 25 Vertice A 25 Vertice A 25 Vertice A 10. Eleventer A 3448 ' KB 10. County Yet 3448 ' KB Notice of INTENTION TO: Subscuence A Notice of INTENTION TO: Subscuence A Vertice A annoon Fuel and annoon Vertice A annoon Fuel and ann	207 South 4th Street - Artesia, N1 68210 I. Fuld and Ical, or Willow Indexignated Local of Noil 600 Iter read and the street read in the North Line as 620 Iter read and the street read in the North Line as 620 Iter read and the street of North Line as 620 Iter read and the street of North Line as 620 Iter read and the street of North Line as 620 Iter read and the street of North Line as 620 Iter read and the street of North Line as 620 Iter read and the street of North Line as 620 Iter read and the street of North Line as 620 Iter read and the street of North Line as 620 Iter read and the street of North Line and 620 Iter read and the street of North Line and 5000 Interest and the street of North Line and 5000 Iter read and the street of North Line and 5000 Iter read and the street of North Line and 5000 Iter read and the street of North Line and 5000 Interead and the street of North Line and 5000 Iter read and the street of North Line and 5000 Iter read and the street of North Line and 5000 Attention Cashed Ter And 5000 Interead and the street of North Line and 5000 Iter read and 5000 Iter read and 50000 Attention Cashed Ter And 5000 Interead and the street of North 20, 1974, plugged well with 35 sacks Class C and sakes and 5000 sacks and 500 sacks on top of retainer. A few days later, found well flowing very slightly. Iter found well flowing very slightly. On March 20, 1974, drilled out cement plug at 1030', set inter the str		Corporation		
Location at Well 200 In the case of the end of the context of the end end the end of the end of the end end of the	Location ad Wolf 100 With Leffer A 660 With Leffer A 660 The East Line, SCHOR MARK NOR INC. 25 Test East Line, SCHOR MARK NOR INC. 185 Test East Line, SCHOR MARK NOR INC. 185 Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County Test East Line, SCHOR MARK NOR INC. 12. County East Line, SCHOR MARK NOR INC. Test East Line, SCHOR MARK NOR INC. 12. County East Line, SCHOR MARK NOR INC. Test East Line, SCHOR MARK NOR INC.		hand Artonia	NM 88210	72
North Little A 660 rest mount at Morth use and 620 rest mean field of the second	A 660 references in the			NA 80210	10. Field and Pool, or Wildcat
The	The		NC NC	orth 620	Undesignated
15. Elevation (Show whether DF, RT, CR, etc.) 3448' KD 12. Gounty 12. Gounty 12. Gounty 14. County 12. Gounty 15. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: 15. County 15. Elevation attricts SUBSEQUENT REPORT OF: 15. County 15. Elevation attricts Subsequent Report of Other Data Subsequent Report of: 15. County 15. Elevation attricts Subsequent Report of: 15. County 15. Elevation attricts Autrement attricts 15. County 15. States Class C attricts Autrement attricts 15. County 15. States Class C attricts Autrement attricts 17. Desciption throught of the attrict attricts Class C attricts Autrement attricts 17. County 15. States Class C attres Class C attricts Autre	15. Elswatten (Show whether DF, RT, GR, etc.) 12. County 3448' KD Eddy NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PROFEMENT ALLOS OF INTENTION OF INTENTION TO: SUBSEQUENT REPORT OF:	UNIT LETTER	JUFEET FROM THEIVE	LINE ANDF	
3448' KB Eddy Atternet Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: Atternet Current PLUE AND ARADOW SUBSEQUENT REPORT OF: Atternet Current PLUE AND ARADOW Converted evillation of the Data Subsequent Report of: Atternet Current PLUE AND ARADOW Converted evillation of the Data Subsequent Report of: Atternet Current Converted evillation of the Data Subsequent PLUE AND ARADOW Atternet Cashe Atternet Cashe Converted evillation of the Data Subsequent PLUE AND ARADOW Atternet Cashe The Data Subsequent of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose On March 20, 1974, plugged well with 35 Sacks Class C at 1368' and 75 sacks at 1318'. On March 22, tagged firm coment at 1076'. The following day, prept to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber-glass tailpipe, spot 80 Sacks Class C case 1 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. <	3448' KB Eddy Adds: KB Eddy NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: NUMBER CARDING PLUE AND ABANDON Itemporal IL MORE PLUE AND ABANDON Itemporal Current Completed Operations (Clearly state all partiment details, and give partment dates, including estimated date of starting any proposed of Completed Operations (Clearly state all partment details, and give partment dates, including estimated date of starting any proposed at 1318'. On March 22, tagged firm cement at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber-glass tailpipe, spot 80 sacks Class C coment 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. Itemporal Item endument of the same end complete to the best of my knowledge and bellef. Item endument endumen	THEEast_ LINE, SECTIO	N 25 TOWNSHIP	L8S RANGE 25E	NMPM.
3448' KB Eddy Add S' KB Eddy NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUE AND ABADON CONVENCE ONLINE ONS. Converse of Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any propose ON March 20, 1974, plugged well with 35 sacks Class C at 1368' and 75 sacks at 1318'. On March 22, tagged firm coment at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out coment plug to 1302', ran retainer with fiber- glass tailpipe, spot 80 sacks Class C cacen the losting for casing leaks testing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect ch	3448' KB Eddy Adds: KB Eddy NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: NUMBER CARDING PLUE AND ABANDON Itemporal IL MORE PLUE AND ABANDON Itemporal Current Completed Operations (Clearly state all partiment details, and give partment dates, including estimated date of starting any proposed of Completed Operations (Clearly state all partment details, and give partment dates, including estimated date of starting any proposed at 1318'. On March 22, tagged firm cement at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber-glass tailpipe, spot 80 sacks Class C coment 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. Itemporal Item endument of the same end complete to the best of my knowledge and bellef. Item endument endumen	mmmmmm	15. Elevation (Show w	hether DF, RT, CR, etc.)	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ATTENDEDIAL WORK PLUC AND ARANDON COMMERCE PLANE PLUS AND COMPLETED TOTAL TOTAL	Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: Attended at work Attended at work Attended at work Attended at work Attended attended at an additional and additional ad		~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~		Eddy
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: ALTERING CASING HELLO AL WORK COMMENT OFILLING OPEN. COMMENT OF ILLING OPEN. COMMENT OFILLING OPEN. OWNER COMMENT OFILING OPEN. OWNER COMMENT OFILING OPEN. OWNER COMMENT OFILING OPEN. OWNER COMMENT OFILING OPEN. ON JULY 25, 1974, drilled over state of the comment at 10761. The following day, point cement at 10421 and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. O	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: NEWFORM REMEDIAL WORK PLUE AND CARNOON ALTERING CASING NULL OR ALTER CASING CHANCE PLANS COMMENCE DRILLING OPHN. OWNER COMMENCE DRILLING OPHN. COMMENCE DRILLING OPHN. ON BERCHENCE TO. COMMENCE DRILLING OPHN. COMMENCE DRILLING OPHN. ON SUBLED COMMENCE TO COMPLEXE OF COMMENCE DRILLI				
Provide NUMBER Provide Addatases Provide Addatases Provide Addatases Provide Addatases Construct construction constructin construction construction construction const	PLUE AND ARABON PLUE AND ARABON PLUE AND ARABON PLUE AND ARABON COMMENT DOWL PLUE AND ARABON Intervention Arabon COMMENT DOWL COMMENT DOWL OTHER COMMENT DOWL COMMENT DOWL VILL OR ALTER CASHE COMMENT DOWL Comment DURING OFFICE OTHER Comment DURING Comment DURING Comment DURING OFFICE OTHER Comment DURING Comment DURING OFFICE Comment DURING OFFICE OTHER Comment DURING OFFICE Comment DURING OFFICE Comment DURING OFFICE OTHER Comment DURING OFFICE Comment DURING OFFICE Comment DURING OFFICE OTHER Comment DURING OFFICE Comment DURING OFFICE Comment DURING OFFICE ON MARCH 20, 1974, plugged well with 35 sacks Class C at 1368' and 75 sacks at 1318'. On March 22, tagged firm cement at 1076'. The following day, prept to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber-glass tailpipe, spot 80 sacks Class C Class C cement 2% Cacl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks is from retainer, suspect channel thru tailpipe. Comment Dug at 1038'; leak is 100 Sacks of Class C 2%			subsi	EQUENT REPORT OF:
COMMENCE ORIGET AND REMEMBED AND AND ADDRESS COMMENCE OR INCLURE OF MALE TEST AND CEMERT TAB COMMENT CASING	COMMENTER OF MANNER PLANS COMMENTER OF MANNER PLANS COMMENTER OF MANNER OF MANNER PLANS COMMENTER OF MANNER OF MANNER PLANS COMMENTER OF MANNER OF MANNER OF MANNER OF MANNER PLANS COMMENTER OF MANNER OF MA				ALTERING CASING
CHARGE PLANS CHARGE PLANS CHARGE PLANS CHARGE PLANS OTHER OTHER OTHER OTHER 7. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work (Starting and Proposed or Starting any proposed at 1318'. On March 22, tagged firm cement at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber-glass tailpipe, spot 80 sacks Class C cement 2% Cacl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% Cacl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. Is. Therefore early that the information above is true and complete to the best of my knowledge and bellef. Wire Marker	CHARGE PLANS CHARGE PLANS CHARGE PLANS CHARGE PLANS CHARGE PLANS OTHER OTHER OTHER OTHER OTHER OTHER 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) set marker, found well flowing very slightly. On March 20, 1974, plugged well with 35 sacks Class C at 1368' and 75 sacks at 1318'. On March 22, tagged firm coment at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber-glass tailpipe, spot 80 sacks Class C cement 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. 18.1 herety certify that the information above is true and complete to the best of my knowledge and bellef. Additional data base is true and complete to the best of my knowledge and bellef. Additional data base is true and complete to the best of my knowledge and bellef.	PERFORM REMEDIAL WORK	PLUG AND ABANDO		PLUG AND ABANDONMENT
OTHER OTHER 0. OTHER 7. Describe Proposed or Completed Operations (Clearly state all periment details, and give pertiment dates, including estimated date of starting any propose work) SEE RULE 1103. 0. March 20, 1974, plugged well with 35 sacks Class C at 1368' and 75 sacks at 1318'. On March 22, tagged firm cement at 1076'. The following day, prep to set marker, found well flowing very slightly. 0. Duty 25, 1974, drilled out cement plug to 1302', ran retainer with fiber-glass tailpipe, spot 80 sacks Class C cement 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. 0. September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. 0. December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. IMAGE MARCH MARCH 10.2 Mark 2. MARM MARM 10.2 Mark 2. Description	orners		CHANCE BLANS		
OTHER	On March 20 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103. On March 20, 1974, plugged well with 35 sacks Class C at 1368' and 75 sacks at 1318'. On March On March 20, 1974, drilled out cement at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber-glass tailpipe, spot 80 sacks Class C cement 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. Ib. I hereby certify that the information above is true and complete to the best of my knowledge and bellef. Watter 210-75	PULL OR ALTER CASING	CHANGE PLANS		
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) size NUL E 1103. On March 20, 1974, plugged well with 35 sacks Class C at 1368' and 75 sacks at 1318'. On March 22, tagged firm cement at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber-glass tailpipe, spot 80 sacks Class C cement 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. 10.2 10.2 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.5 10.4 10.4 10.4 10.4 10.4 10.4 10.4 10.5 10.4	7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) site work is the trans. On March 20, 1974, plugged well with 35 sacks Class C at 1368' and 75 sacks at 1318'. On March 22, tagged firm cement at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber-glass tailpipe, spot 80 sacks Class C cement 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. 10.2 11.1 bereby certify that the Information above is true and complete to the best of my knowledge and bellef. Automatication and the location is now ready for inspection. 11.1 bereby certify that the Information above is true and complete to the best of my knowledge and bellef. Automatication of the base of the provide to the best of my knowledge and bellef. Automatication of the base of the base of my knowledge and bellef. Automatication above is true and complete to the best of my knowledge and bellef. Automatication of the base of the base of my knowledge and bellef. Automatication of the base of the base of my knowledge and bellef. Automatication of the base of the base of my knowledge and bellef. Automatication of the base of the base of my knowledge and bellef. Automatication of the base of the base of				
On March 20, 1974, plugged well with 35 sacks Class C at 1368' and 75 sacks at 1318'. On March 22, tagged firm cement at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber- glass tailpipe, spot 80 sacks Class C cement 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. 18.1 hereby centify that the information above is true and complete to the best of my knowledge and belief.	On March 20, 1974, plugged well with 35 sacks Class C at 1368' and 75 sacks at 1318'. On March 22, tagged firm cement at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber- glass tailpipe, spot 80 sacks Class C cement 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. 18.1 hereby centify that the information above is true and complete to the best of my knowledge and belief.				
On March 20, 1974, plugged well with 35 sacks Class C at 1368' and 75 sacks at 1318'. On March 22, tagged firm cement at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber- glass tailpipe, spot 80 sacks Class C cement 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. 18.1 hereby centify that the information above is true and complete to the best of my knowledge and belief.	On March 20, 1974, plugged well with 35 sacks Class C at 1368' and 75 sacks at 1318'. On March 22, tagged firm cement at 1076'. The following day, prep to set marker, found well flowing very slightly. On July 25, 1974, drilled out cement plug to 1302', ran retainer with fiber- glass tailpipe, spot 80 sacks Class C cement 2% CaCl from 1302-1000', set retainer at 1042' and squeezed to 500 psi, dumped 50 sacks on top of retainer. A few days later, found well flowing very slightly. On September 17, 1974 ran tubing and packer in hole testing for casing leaks tested casing to 1200 psi, casing okay, found cement plug at 1038'; leak is from retainer, suspect channel thru tailpipe. On December 27, 1974, drilled retainer, cement and tailpipe, clean out to 1354'. Spotted 100 sacks of Class C 2% CaCl at 1354', set wireline retainer at 1040'. Marker is set, location cleaned and the location is now ready for inspection. 18.1 hereby centify that the information above is true and complete to the best of my knowledge and belief.	7. Describe Proposed or Completed Op	perations (Clearly state all pertin	ent details, and give pertinent dates,	including estimated date of starting any propose
APPROVED BY DATE DATE	APPROVED BY DATE DATE	at 1318'. On Marc prep to set marker On July 25, 1974, glass tailpipe, sp retainer at 1042' retainer. A few d On September 17, 1 tested casing to 1 from retainer, sus On December 27, 19 1354'. Spotted 10 at 1040'. Marker	h 22, tagged fir: , found well flo drilled out ceme oot 80 sacks Cla and squeezed to ays later, found .974 ran tubing a .200 psi, casing spect channel thr .74, drilled reta	m cement at 1076'. wing very slightly nt plug to 1302', 1 ss C cement 2% CaC 500 psi, dumped 50 well flowing very nd packer in hole okay, found cement u tailpipe. iner, cement and t C 2% CaCl at 1354	The following day, ran retainer with fiber- l from 1302-1000', set sacks on top of slightly. testing for casing leaks plug at 1038'; leak is ailpipe, clean out to ', set wireline retainer ocation is now ready
APPROVED BY DATE DATE	APPROVED BY DATE DATE				1
APPROVED BY DATE DATE	APPROVED BY DATE DATE	18. I hereby certify that the informatio	n above is true and complete to t	he best of my knowledge and belief.	
APPROVED BY DATE	APPROVED BY DATE	(Fri)		Destador	DATE
· ·	•	5 V AL			
·	•		V I		
·	•	A RROUGH BY		LE	DATE
	CONDITIONS OF APPROVACE IF BRIT		Y:		