

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-20858
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Vandiver CN Com
8. Well No.	1
9. Pool name or Wildcat	Atoka Morrow
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>E 2</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>18</u> Township <u>18S</u> Range <u>26E</u> NMPM Eddy County
5. Pool name or Wildcat Atoka Morrow	6. Lease Name or Unit Agreement Name Vandiver CN Com
7. Lease Name or Unit Agreement Name Vandiver CN Com	8. Well No. 1
9. Pool name or Wildcat Atoka Morrow	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon as follows:

1. Set CIBP at 8616' and cap with 35' of cement.
2. Determine freepoint of 5-1/2" casing. NOTE: Temperature Survey indicates top of cement at 8180'. Cut and pull as much casing as possible.
3. Spot a 50 sack cement plug across 5-1/2" casing stub (half in and half out of plug). WOC. Tag plug.
- * 4. Spot a 30 sack cement plug from 4337-4220'. WOC. Tag plug. *OK*
5. Spot a 30 sack cement plug from 2251-2134'. WOC. Tag plug. *OK*
- * 6. Spot a 30 sack cement plug from 1262-1153'. WOC. Tag plug.
- * 7. Spot a 10 sack cement plug at surface.
8. Install regulation abandonment marker.

Plugging mud between plugs.

NOTIFY OGD-ARTESIA (505-748-1283) 24 HOURS PRIOR TO COMMENCING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE Aug. 20, 1996
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

SEP 5 1996

APPROVED BY _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

* $\geq 100'$ plug 6000-6100'.
* $\geq 100'$ plug across 13 3/8" shoe Tag.