

COPIES RECEIVED	
DISTRIBUTION	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

RECEIVED

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.		

## SUNDRY NOTICES AND REPORTS ON WELLS APR 5 - 1974

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator David Fasken		8. Farm or Lease Name Vandiver "7" Sidetrack	
3. Address of Operator 608 First Natl. Bank Bldg., Midland, Texas 79701		9. Well No. 1	
4. Location of Well UNIT LETTER M, 660' FEET FROM THE South LINE AND 660' FEET FROM THE West LINE, SECTION 7 TOWNSHIP 18-S RANGE 26-E N.M.P.M.		10. Field and Pool or Wildcat Undesignated West Atoka Morrow	
15. Elevation (Show whether DF, RT, GR, etc.) 3431' GL.		12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS	<input type="checkbox"/>	OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-24-74 Set Cement Plugs as follows (Approved per phone conversation w/Mr. Bill Gressett (2-21-74)

Plug #	Location	Depth	Length	Material
Plug #1	Morrow	8600'	- 8750'	75 SXS
Plug #2	Atoka	8330'	- 8430'	30 SXS
Plug #3	Canyon	7400'	- 7500'	30 SXS
Plug #4	Wolfcamp	5650'	- 5750'	30 SXS
Plug #5	Abbo	4320'	- 4330'	30 SXS
Plug #6	Glorietta	2200'	- 2300'	30 SXS
Plug #7	8-5/8" Csg. Shoe	1200'	- 1400'	100 SXS
Plug #8	Surface	10 -	Surface	10 SXS

2-25 Move out Rotary tools. Waiting on reserve pits to dry to level and return location to contour of land.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Michael Claiborne TITLE Agent DATE 4-4-74

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: