

COPIES RECEIVED	
TRIBUTION	
FE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

APR 3 - 1974

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Vandiver "7" Sidetrack	
9. Well No.	
1	
Undesignated or Wildcat	
West Atoka Morrow	
12. County	
Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS **D. C. C.**
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DISCONTINUED WELL. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator
	David Fasken
3. Address of Operator	608 First Natl. Bank Bldg., Midland, Texas 79701
4. Location of Well	UNIT LETTER <u>M</u> <u>660'</u> FEET FROM THE <u>South</u> LINE AND <u>360'</u> FEET FROM THE <u>West</u> LINE, SECTION <u>7</u> TOWNSHIP <u>18-S</u> RANGE <u>26-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)	3431' GL.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-24-74 Set Cement Plugs as follows (Approved per phone conversation w/Mr. Bill Gressett (2-21-74)

Plug #1	Morrow	8600' - 8750'	75	sxs
Plug #2	Atoka	8330' - 8430'	30	sxs
Plug #3	Canyon	7400' - 7500'	30	sxs
Plug #4	Wolfcamp	5650' - 5750'	30	sxs
Plug #5	Abbo	4320' - 4330'	30	sxs
Plug #6	Glorietta	2200' - 2300'	30	sxs
Plug #7	8-5/8" Csg. Shoe	1200' - 1400'	100	sxs
Plug #8	Surface	10 - Surface	10	sxs

2-25 Move out Rotary tools. Waiting on reserve pits to dry to level and return location to contour of land.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Michael Claborn TITLE Agent DATE 4-4-74
APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE JUN 4 1974
CONDITIONS OF APPROVAL, IF ANY: