

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI. CATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		RECEIVED	
2. NAME OF OPERATOR Texaco Producing Inc. ✓		7. UNIT AGREEMENT NAME Lea "D"	
3. ADDRESS OF OPERATOR P.O. Box 730, Hobbs, NM 88240		8. FARM OR LEASE NAME Lea "D"	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Letter K, 1980' FSL & 1980' FWL		9. WELL NO. 9	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3825' GL	
10. FIELD AND POOL, OR WILDCAT GB Jackson/Fren Seven Rvrs		11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA Sec. 26, T-17-S, R-31-E	
12. COUNTY OR PARISH Eddy		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/03/90 thru 12/04/90

- 1) MIRU PU. TOH laying dn rods, tbg & pmp.
- 2) TIH w/WS.
- 3) Set cmt rtnr @ 2580'. Sqz w/75' sx C1 C.
- 4) Load hole w/mud.
- 5) Spt 25 sx plug @ 2185-1940'.
- 6) Spt 30 sx plug @ 860-565'.
- 7) Spt 6 sx plug 50'-surf.
- 8) Cut off WH. Instld marker. Clnd locn.

RECEIVED
DEC 28 10 56 AM '90
CARLOS J. FLORES
AREA H/O OPERATIONS

18. I hereby certify that the foregoing is true and correct

SIGNED Richard DeArto

TITLE Engineering Technician

DATE 12/21/90

(This space for Federal or State office use)

APPROVED BY Chris S. [Signature]

TITLE Area H/O Operations

DATE 1-7-91

CONDITIONS OF APPROVAL, IF ANY:

When the well is completed,
and the information is completed,

*See Instructions on Reverse Side