ENERGY AND MINERALS DEPAR		
NO. OF COPIED DECEIVED	JIL CONSERVATION DIVISIC	
DISTRIBUTION	P. O. BOX 2088	Form C-103
BANTA FE	SANTA FE, NEW MEXICO 87501	Revised 10-1-7
PILE	RECEIVED	5a. Indicate Type of Lense
U.S.O.S.		[]
LAND OFFICE		State Fee X
OPERATOR	APR 3 1980	5. State Oil & Gas Lease No.
		1
SUN LEO NOT USE THIS FORM FOR	NDRY NOTICES AND REPORTS ON WELLS O. C. D.	
OIL CAD WELL X		7, Unit Agreement Name
Name of Ocerator ARCO C	other-	8. Farm or Lease Name
Division of	Atiantic Richfield Company	Stirling Com.
, Address of Operator		9. Well No.
Box 1710, Hobbs, New	√ Mexico 88240 ✓	1
Location of Well		10. Field and Pool, or Wildcat
r	1650	1
UNIT LETTER F . 1650 FEET FROM THE NORTH LINE AND 1980 FEET PRO		Red Lake Penn Gas
	·	
THE West LINE, SE	ECTION 7 TOWNSHIP 18S RANGE 27E NMPN	
	NMPh	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
; ;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;	3288' GR	Eddy ( ) [ ] [ ]
Chec	ck Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
	E INTENT.ON 70	IT REPORT OF:
ERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	. —
$\overline{}$		ALTERING CASING
EMPORABILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT 🔀
ULL OR ALTER CABING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
7. Describe Proposed or Completed	d Operations (Clearly state all pertinent details, and give pertinent dates, including	g estimated date of starting any proposed
work) SEE RULE 1103.		•
40 sx Cl C cmt w/2% (below retr. Dmpd 24 5½" OD csg @ 5160-61 Ran temp survey, indi 2600', could not brea 3250#, pmpd 80 BFW w/	ell, installed BOP, POH w/compl assy. RIH w/cmt re 9174' w/50 sx C1 C cmt w/2% CaC1. RIH w/cmt retr, CaCl to retr @ 8720'. Squeezed 12 sx into perfs 87 sx cmt on top of retr. Ran CBL 5400' to surface, 'w/2 JSPF. RIH w/cmt retr, set @ 5112'. Pmpd 950 icated TOC @ 2700'. Perf'd 5½" csg 2675-2677' w/2 ak circ thru perfs. Perforated 1950-52'. Set pkr/no returns. WIH w/tbg OE to 2144'. Spotted 35 sx	set retr @ 8720'. Spotte 770-77', 4 sx cmt in csg TOC @ 5190'. Perf'd D sx C1 C cmt w/2% CaCl. JSPF. Perforated @
tooo. Tutt tog up t	to 30', spot 30' C1 C cmt plug @ surface. P&A effe	ective 3/30/80. Final
tooo. Tutt tog up t	to 30', spot 30' Cl C cmt plug @ surface. P&A effe	ective 3/30/80. Final
tooo . Tuil tog up t	to 30', spot 30' Cl C cmt plug @ surface. P&A effe	Post 2 40  H 1 1 4
rooo . ruii tog up (	to 30', spot 30' Cl C cmt plug @ surface. P&A effe	ective 3/30/80. Final
Report.	to 30', spot 30' C1 C cmt plug @ surface. P&A effe	ective 3/30/80. Final
Report.	to 30°, spot 30°C1°C cmt plug @ surface. P&A effe	ective 3/30/80. Final
Report.	to 30°, spot 30°C1°C cmt plug @ surface. P&A effe	ective 3/30/80. Final

CONDITIONS OF APPROVAL, IF ANYI