

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-015-21543

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-7244

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Empire Abo Unit "L"

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

BP America Production Company

8. Well No.

141

3. Address of Operator

P.O. Box 1089 Eunice, NM 88231

9. Pool name or Wildcat

Empire Abo

4. Well Location

Unit Letter N : 1050 Feet From The S Line and 1360 Feet From The W Line

Section 2 Township 18S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3516.4' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Workover ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6158' PBD: 6118' PERFS: 6005-6108' (old), 5714-5975' (new)

02.25.02: MIRUPU. NDWH. NUBOP. Unset pkr & TOH w/tbg.

02.26.02: Finish TOH. Tbg plugged due to paraffin. Hot oil tbg.

02.27.02: Finish TOH w/tbg. RIH w/bit & bailer. CO from 6002-6117'. POH w/36 stds.

02.28.02: TOH w/bit & bailer. TIH w/RBP & pkr. Testing tbg to 5000# psi below slips, set RBP @ 5968'. RU 1 jt. Set pkr @ 5937'. Test plug to 600# psi, 15 mins, held OK.

03.01.02: Rls pkr & swb 109 bbls. Retrieve RBP & TOH.

03.04.02: RU & perf 5714-19', 5750-54', 5788-92', 5812-18', 5826-38', 5858-60', 5872-76' 5908-28', 5940-50', 5968-75', 2 JSPF. TIH w/RBP & pkr to 6110'. Spot 500 gals 15% HCL. PU to 5980' & set RBP. PU to 5610' & set pkr. Pmp 3700 gals 15% HCL

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Kellie D. Murrish

TITLE Sr. Administrative Assistant

DATE 04.02.02

TYPE OR PRINT NAME Kellie D. Murrish

TELEPHONE NO. 505-394-1649

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APR 05 2002

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Empire Abo Unit L-141
30-015-21543
Workover Operations

03.04.02: Retrieve RBP & start out of hole.

03.05.02: Finish TOH. TIH w/production tbgs. NDBOP. NUWH. Swab well. 2-3/8" tbgs set @ 6044'. SN set @ 6056'. Return well to production. In 24 hrs. pmp 0 BO, 0 BW, 15 MCF.