PHONE (505) 623 . 6601



## HARVEY E. YATES COMPANY, INC.

SUITE 1000 SECURITY NATIONAL BANK BUILDING

ROSWELL, NEW MEXICO - 88201

October 15, 1976

W. A. Gressett State of New Mexico Oil Conservation Commission Post Office Drawer DD Artesia, New Mexico 88210

> Re: Yates State #6 H- 32-18-30 Sec 31, T-185, R-30E Deviation Survey

Dear Mr. Gressett:

In searching our files we cannot find the Totco charts run on the above well. However on our daily drilling reports there is evidence that a deviation survey was run at 2030' with 1° deviation and another at rotary TD of 2600' with a deviation of  $1/4^{\circ}$ . We are confident the hole is striaght because we ran 2600' of 7" pipe in this 7 7/8" hole in order to seal off a water zone.

Yours truly, Fred G. Yates

FGY:amp

## RECEIVED

OCT 1 8 1976

D. C. C.