

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-21622
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. F-2211
7. Lease Name or Unit Agreement Name
8. Well No. 6
Pool name or Wildcat Benson Queen Grayburg-North
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3400' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Yates Energy Corporation	3. Address of Operator P. O. Box 2323, Roswell, New Mexico 88202
4. Well Location Unit Letter H : 1980 Feet From The North Line and 990 Feet From The East Line Section 32 Township 18 S Range NMPM Eddy County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3400' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PULL OR ALTER CASING <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) Set a 4-1/2" CIBP at 2900' - Place ^{35'}~~20'~~ plug on CIBP.
- 2.) Set a 25 sack plug from 2400' - 2700'.
- 3.) Cut 4-1/2" casing at 1300' - pull casing and lay down.
- 4.) Set a 50 sack plug from 1200' to 1390'. Tag Plug.
- 5.) Set a 50 sack plug from 344' to 544'. TAG.
- 6.) Set a 10 sack plug at surface - weld plate on 8-5/8" casing with Dry Hole Marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James F. O'Briant TITLE Agent for Yates Energy Corp. DATE 1/16/98
TYPE OF PRINT NAME James F. O'Briant TELEPHONE NO. (915) 683-5511

(This space for State Use)

APPROVED BY Mrs. S. [Signature] TITLE Field Rep. II DATE 2-12-98
CONDITIONS OF APPROVAL, IF ANY:

