LIKUN JACKSON INC.

CEMENTING AFFIDAVIT

I, <u>Gurry Curr</u> , being of lawfu	
the facts harein below set out do stat	e: I am employed by Byron Jackson Inc.
on <u>9-25</u> , 19 <u>75</u> , Byron J	
operation herein described for Atlant	
Well No. <u>J-231</u> on the <u>Empire</u>	
located in <u>Prop</u> County,	State of <u>New Merico</u>
CASING CEXEXTING: Name or type of str	ing was Surface . Information
provided by the Customer Company state	is that the casing was $8 = 5/3$ in. O.D.
set in <u>lig</u> inch hole, and that th	e casing depth set was <u>1021</u> feet.
For this job the following materials w	vere used:
élőő élesete – Gilass C Coment	at in in the set of the
<u></u>	RECEIVED
	SEP 3 0 1975
The second s	
	O. C. C.
	ARTESIA, OFFICE
10 - Lucian - Alen	ARTESIA, DFFICE
	cement was circulated out of the well.
Did Not Oireulate	cement was circulated out of the well.
Did Not Gireulate An estimatedsacks of excess 	cement was circulated out of the well. the Customer Company states that the
Did Not Gireulate An estimatedsacks of excess <u>OLARNO PLUG</u> : Information provided by hole size wasinches, and t	the Customer Company states that the cotal depth wasfeet. For
Did Not Gireulate An estimatedsacks of excess 	the Customer Company states that the cotal depth wasfeet. For
Did Not Givenlate An estimatedsacks of excess <u>OIRCENT PLUG</u> : Information provided by hole size wasinches, and t this job the following materials were	the Customer Company states that the cotal depth wasfeet. For
Did Not Givenlate An estimatedsacks of excess <u>OIRCENT PLUG</u> : Information provided by hole size wasinches, and t this job the following materials were	the Customer Company states that the cotal depth was feet. For used to place plugs as indicated:
Did Not Givenlate An estimatedsacks of excess <u>OIRCENT PLUG</u> : Information provided by hole size wasinches, and t this job the following materials were	the Customer Company states that the cotal depth was feet. For used to place plugs as indicated:
Did Not Giveulate An estimatedsacks of excess <u>CILENT PLUG</u> : Information provided by hole size wasinches, and t this job the following materials were Plug fromft. toft.	the Customer Company states that the cotal depth wasfeet. For used to place plugs as indicated: withsacks of
Did Not Givenlate An estimatedsacks of excess <u>OIRCENT PLUG</u> : Information provided by hole size wasinches, and t this job the following materials were	the Customer Company states that the cotal depth was feet. For used to place plugs as indicated:

SIGNED:	BYRON JACKSON INC.	1
BY-	Gerry Cuy Jesus	Jul
DATE:	9-25-75	