

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

NM Roswell District
Modified Form No.
NM060-3160-4

c/sf

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		FEB 26 '90	
2. NAME OF OPERATOR Hondo Drilling Co. ✓		3a. Area Code & Phone No. (915) 882-9401 ARTESIA OFFICE	
3. ADDRESS OF OPERATOR P. O. Drawer 2516, Midland, TX 79702-2516			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1,650' FNL and 1,980' FEL, Sec. 31, T-18-S, R-29-E, Eddy County, NM NMPM			
14. PERMIT NO. 21804 30-015-22549		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3,421' GR.	
12. COUNTY OR PARISH Eddy		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETION	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>	(Other)	<input type="checkbox"/>		

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- 2-9-90 Set 5 1/2" Elite 17-20 lb Bridge Plug at 10,850'.
Cemented top of Bridge Plug with Dump Bailer, Four sacks cement, plug back depth 10,810'.
- 2-10-90 Ran 2 3/8" Tubing and 5 1/2" Guiberson Packer, set at 10,950' and perforated well, Halliburton Tubing Gun from 10,170' - 10,180' and 10,222' - 10,232', two shots per foot.
- 2-12-90 Acidize well with 4,000 gal. 15% acid and 75 ball sealers, treating pressure 3,800 lb to 5,900 lb, average rate 3.4 bbl per min.
- 2-13-90 Flowing well on 1/2" choke to clean up load water and acid water. Venting and burning 1,750 MCF of gas. Shut-in pressure 2,750 lbs.

ACCEPTED FOR RECORD

FEB 28 1990

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE President

DATE Feb. 19, 1990

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side