STATE OF NEW MEXICO	·		
ENERGY AND MINERALS DEPARTMENT		TION DIVISION	
we, or contenticites	OIL CONSERVA		Form C-103
DISTRIBUTION	RECEIVED BY O. BO	X 2088	Revised 10-1-79
SANTA FE	"SANTA FE, NEW	MEXICO 87501	
PILE D	NOV -7 1986		Sa. Indicate Type of Lease
U.S.O.S.	MUA -1 1999		State X Fee
OPERATOR	O, C, D.		5. State Oil & Gas Lease No.
			State 647
SUNDRY	ARTESIA, OFFICE	WET 1 6	VIIIIIIIIIIIIIII
Tule	NOTICES AND REPORTS ON	ACK TO A DIFFERENT RESERVOIR.	VIIIIIIIII
	FOR PERMIT -" (FORM C-101) FOR SUC	H PROPOSACS.)	7. Unit Agreement Name
1. OIL . GAS .			7. Gill rigidament rema
were were	OTHER- P&A		
2. Name of Operator			8. Farm or Lease Name
Yates Petroleum Corporat	ion		H-Y State GH
J. Address of Operator			9. Well No.
105 South 4th St., Artes	sia, NM 88210		1
4. Location of Well		10. Field and Pool, or Wildcat	
72 1090	South	LINE AND 1980 PEET FRO	Artesia-O-G-SA
UNIT LETTER	FEET FROM THE	LINE AND PEET PRO	"HILLIHITINA"
77	21 100	200	
THE WEST LINE, SECTION	31 TOWNSHIP 18S	HANGE 40E HMP	
		DC DT CD	viiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii
	15. Elevation (Show whether		12. County
	3548' GR		Eddy ()
16. Check An	propriate Box To Indicate N	Nature of Notice, Report or O	ther Data
NOTICE OF INT	• •	-	IT REPORT OF:
" NOTICE OF INT	ENTION TO:	00001401.	
_			ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT X
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	- · · · · · · · · ·
		OTHER	† 1
	· —	V	
OTHER			
			a suisaved days of staying any proposed
	ations (Clearly state all pertinent det		ng estimated date of starting any proposed
17. Describe Proposed or Completed Opera	ations (Clearly state all pertinent det		ng estimated date of starting any proposed
17. Describe Proposed or Completed Operatuork) SEE RULE 1 103.			ng estimated date of starting any proposed
17. Describe Proposed or Completed Operations) see Rule 1603. Plugged well as follows:	•		ng estimated date of starting any proposed
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10#	: mud.	ails, and give pertinent dates, includit	
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20	: mud. 015' w/65 sx Class C w/	ails, and give pertinent dates, including a second of the	
17. Describe Proposed or Completed Operations, SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C	3% CaCl2. Tagged plug	
17. Describe Proposed or Completed Operations, SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43	: mud. 015' w/65 sx Class C w/	3% CaCl2. Tagged plug	
17. Describe Proposed or Completed Operations, SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C	3% CaCl2. Tagged plug	
17. Describe Proposed or Completed Operations, SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43	mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas	3% CaCl2. Tagged plug	
Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30	mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas	3% CaCl2. Tagged plug	
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and inse	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas stall dry hole marker.	3% CaCl2. Tagged plug	
Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas stall dry hole marker.	3% CaCl2. Tagged plug	
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and inse	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas stall dry hole marker.	3% CaCl2. Tagged plug	
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and inse	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas stall dry hole marker.	3% CaCl2. Tagged plug	at 1805'.
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and inse	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas stall dry hole marker.	3% CaCl2. Tagged plug	at 1805'.
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and inse	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas stall dry hole marker.	3% CaCl2. Tagged plug	at 1805'. Part ID-2
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and inse	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas stall dry hole marker.	3% CaCl2. Tagged plug	at 1805'. Part ID-2
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and inse	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas stall dry hole marker.	3% CaCl2. Tagged plug	Post ID-2 11-14-86
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and inse	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas stall dry hole marker.	3% CaCl2. Tagged plug	at 1805'. Part ID-2
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and inse	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas stall dry hole marker.	3% CaCl2. Tagged plug	Post ID-2 11-14-86
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and inse	: mud. 015' w/65 sx Class C w/ 34-279' w/35 sx Class C O'-surface w/22 sx Clas stall dry hole marker.	3% CaCl2. Tagged plug	Post ID-2 11-14-86
17. Describe Proposed or Completed Oper work) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and ins Plugging completed 11-6-	mud. 015' w/65 sx Class C w/ 034-279' w/35 sx Class C 0'-surface w/22 sx Clas stall dry hole marker86.	ails, and give pertinent dates, including 3% CaCl2. Tagged plug Neat. s C Neat.	Post ID-2 11-14-86
17. Describe Proposed or Completed Operations) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and inse	mud. 015' w/65 sx Class C w/ 034-279' w/35 sx Class C 0'-surface w/22 sx Clas stall dry hole marker86.	ails, and give pertinent dates, including 3% CaCl2. Tagged plug Neat. s C Neat.	Post ID-2 11-14-86
17. Describe Proposed or Completed Oper work) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and ins Plugging completed 11-6-	mud. 015' w/65 sx Class C w/ 034-279' w/35 sx Class C 0'-surface w/22 sx Clas stall dry hole marker86.	ails, and give pertinent dates, including 3% CaCl2. Tagged plug Neat. s C Neat.	Post ID-2 11-14-86
17. Describe Proposed or Completed Oper work) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and ins Plugging completed 11-6-	mud. 015' w/65 sx Class C w/34-279' w/35 sx Class C 0'-surface w/22 sx Class stall dry hole marker86.	3% CaCl2. Tagged plug Neat. S C Neat.	Post ID-2 11-14-86 P+A
17. Describe Proposed or Completed Oper work) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and ins Plugging completed 11-6-	mud. 015' w/65 sx Class C w/34-279' w/35 sx Class C 0'-surface w/22 sx Class stall dry hole marker86.	ails, and give pertinent dates, including 3% CaCl2. Tagged plug Neat. s C Neat.	Post ID-2 11-14-86
17. Describe Proposed or Completed Oper work) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and ins Plugging completed 11-6-	mud. 015' w/65 sx Class C w/34-279' w/35 sx Class C 0'-surface w/22 sx Class stall dry hole marker86.	3% CaCl2. Tagged plug Neat. S C Neat.	Post ID-2 11-14-86 P+A
17. Describe Proposed or Completed Oper work) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and ins Plugging completed 11-6-	mud. 015' w/65 sx Class C w/34-279' w/35 sx Class C 0'-surface w/22 sx Class stall dry hole marker86.	3% CaCl2. Tagged plug Neat. S C Neat.	Post ID-2 11-14-86 P+A
17. Describe Proposed or Completed Oper work) SEE RULE 1703. Plugged well as follows: Circulate hole with 10# Plug #1 20 Plug #2 43 Plug #3 30 Cut off wellhead and ins Plugging completed 11-6-	mud. 015' w/65 sx Class C w/34-279' w/35 sx Class C 0'-surface w/22 sx Class stall dry hole marker86.	3% CaCl2. Tagged plug Neat. S C Neat.	Post ID-2 11-14-86 P+A