

8. ANCILLARY FACILITIES:

A. None required.

9. WELLSITE LAYOUT:

A. Exhibit "D" is included showing well site layout. No unusual amount of cut or fill will be needed. It is a relatively flat location.

B. We plan to line the pit with a plastic pit liner.

10. PLANS FOR RESTORATION OF THE SURFACE:

A. If the well is completed as a producing well, we will knock down pits and smooth out the surface. If not productive, in addition to the above, we will level the location.

11. OTHER INFORMATION:

A. The surface is Federal surface.

B. The topography consists of gently rolling sand and caliche hills with greasewood, mesquite and cacti. No wildlife with the exception of rattlesnakes and jack rabbits were noted.

12. OPERATOR'S REPRESENTATIVE:

The responsible field representatives are as follows:

Johnny Gray  
Gray Pumping Service  
1806 Sears  
Artesia, New Mexico 88210  
Office Phone: 746-3895  
Radio Dispatch: 746-4302 - Unit 231  
Home Phone: 746-3895

Fred G. Yates  
Harvey E. Yates Company, Inc.  
1000 Security National Bank Building  
Roswell, New Mexico 88201  
Office Phone: 623-6601  
Home Phone: 622-5387