District Office		esources Department	Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240			
P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO		WELL API NO.
	P.O. Box 208		30-015-22045
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	8/504-2088	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		V	6. State Oil & Gas Lease No. L-4954
	ES AND REPORTS ON WEL	15	
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVO	ES AND REPORTS ON WELL OSALS TO DRILL OR TO DEEPEN OIR. USE "APPLICATION FOR PER 01) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
I. Type of Well: OIL GAS WELL WELL	OTHER		Four Dinkus GV State
WELL WELL			8. Well No.
YATES PETROLEUM CORPORAT	TION		1
3. Address of Operator			9. Pool name or Wildcat
105 South 4th St., Artes	sia, NM 88210		Wildcat Glorieta Yeso
4 Well Location			
Unit Letter0 :660	_ Feet From The South	Line and198	BO Feet From TheEast Line
Section 16	Township 18S Ra	ange 25E	NMPM Eddy County
777777777777777777777777777777777777777			<i>\////////////////////////////////////</i>
	3551'		V/////////////////////////////////////
	ppropriate Box to Indicate	Nature of Notice, I	Report, or Uner Data
NOTICE OF INTE	ENTION TO:	SU	BSEQUENT REPORT OF:
	[]		
		REMEDIAL WORK	
	CHANGE PLANS	COMMENCE DRILLIN	NG OPNS. PLUG AND ABANDONMENT X
	· · ·		— —1
PULL OR ALTER CASING		CASING TEST AND	
DTHER:		OTHER:	
		<u> </u>	I the second days of second second
12. Describe Proposed or Completed Operation	ms (Clearly state all pertinent details, a	und give periment dates, inc	luding estimated date of starting any proposed
work) SEE RULE 1103.		. ·	luccing operations Moved
6-17-95 - Notified Ray	Smith w/OCD - Artesi	a of commencing	g plugging operations. Moved
in and rigged up pullir	ng unit. Nippled dow	n pumping unit	. FOOD WITH FOUS and pump.
	with tubing, perforate	ed sub and mud	anchor. Rissey in willerine.
Nipplea up BOP. POOH V	not at 2186' Rigged	down wireline	(a) a first of the second sec second second sec
man /r 1/011 (TDD and c		down writerine	. THE WELCH SHUTHELAND LABBER
TIH $w/5-1/2''$ CIBP and s	a 50 bble plue mud fr	om 2186' to su	rface. Mixed and pumped 10 sacks
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted	d 52 bbls plug mud fr	om 2186' to su asing) POOH (rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132	om 2186' to su asing). POOH v 0-1070' (in 5-	・ 「「中」 with Cub ingland fagged rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed 1/2" casing)にで何句句 with tubing
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mood 30 sacks Class C	com 2186' to su casing). POOH v 20-1070' (in 5- 2 cement from 4	・ 「「前 with Cub ingland fagged rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed 1/2" casing)、 デ約6日 with tubing 43-193' (in 5-1/2" casing).
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C ' Mixed and numped	om 2186' to su asing). POOH v 0-1070' (in 5- cement from 4 10 sacks Class	. Fin with tub ingrand ragged rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed 1/2" casing) 7 F00H with tubing 43-193' (in 5-1/2" casing). C(dement From '50 Cto surface.
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 DOOH with tubing to 50	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped	om 2186' to sub- casing). POOH v 0-1070' (in 5- cement from 4- 10 sacks Class bed location.	. Fin with tub hgrann fagged rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed 1/2" casing). 7 f00B with tubing 43-193' (in 5-1/2" casing). C(Cement From '50 For surface. Installed regulation abandonment
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 POOH with tubing. Nipp marker. PLUGGED AND AN	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped pled down BOP. Clean BANDONED - FINAL REPO	om 2186' to sub asing). POOH v 20-1070' (in 5- cement from 4 10 sacks Class ned location. DRT. Plugging	. Fin with tub ingrand ragged rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed 1/2" casing) 7 F00H with tubing 43-193' (in 5-1/2" casing). C(dement From '50 Cto surface.
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 DOOH with tubing to 50	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped pled down BOP. Clean BANDONED - FINAL REPO	om 2186' to sub asing). POOH v 20-1070' (in 5- cement from 4 10 sacks Class ned location. DRT. Plugging	. Fin with tub hgcann fagged rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed 1/2" casing), 7 f00B with tubing 43-193' (in 5-1/2" casing). C(cement from '50 for surface. Installed regulation abandonment
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 POOH with tubing. Nipp marker. PLUGGED AND AN	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped pled down BOP. Clean BANDONED - FINAL REPO	om 2186' to sub asing). POOH v 20-1070' (in 5- cement from 4 10 sacks Class ned location. DRT. Plugging	. Fin with tub hgrann fagged rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed 1/2" casing). 7 f00B with tubing 43-193' (in 5-1/2" casing). C(Cement From '50 For surface. Installed regulation abandonment
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 POOH with tubing. Nipp marker. <u>PLUGGED AND AI</u> Plugging witnessed by N	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped pled down BOP. Clean BANDONED - FINAL REPO Mike Stubblefield w/O	om 2186' to sub- casing). POOH of 20-1070' (in 5- C cement from 4- 10 sacks Class ned location. ORT. Plugging OCD - Artesia.	. Fin with tub hgcann fagged rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed 1/2" casing), 7 f00B with tubing 43-193' (in 5-1/2" casing). C(cement from '50 for surface. Installed regulation abandonment
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 POOH with tubing. Nipp marker. PLUGGED AND AN	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped pled down BOP. Clean BANDONED - FINAL REPO Mike Stubblefield w/O	om 2186' to sub- casing). POOH of 20-1070' (in 5- 2 cement from 4- 10 sacks Class ned location. ORT. Plugging OCD - Artesia.	. Fin with tub hgrann ragged rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed 1/2" casing i food with tubing 43-193' (in 5-1/2" casing). C Gament From '50 Foo surface. Installed regulation abandonment completed 6-16-95. NOTE:
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 POOH with tubing. Nipp marker. <u>PLUGGED AND AI</u> Plugging witnessed by N	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped pled down BOP. Clean BANDONED - FINAL REPO Mike Stubblefield w/O	om 2186' to sub- casing). POOH of 20-1070' (in 5- 2 cement from 4- 10 sacks Class ned location. ORT. Plugging OCD - Artesia.	. Fin with tub hgcann fagged rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed 1/2" casing), 7 f00B with tubing 43-193' (in 5-1/2" casing). C(cement from '50 for surface. Installed regulation abandonment
TIH w/5-1/2" CIBP and so CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 POOH with tubing. Nipp marker. <u>PLUGGED AND AN</u> Plugging witnessed by N I hereby certify that the information above is true skonature	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped pled down BOP. Clean BANDONED - FINAL REPO Mike Stubblefield w/O	om 2186' to sub- casing). POOH of 20-1070' (in 5- 2 cement from 4- 10 sacks Class ned location. ORT. Plugging OCD - Artesia.	Clerk
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 POOH with tubing. Nipp marker. <u>PLUGGED AND AI</u> Plugging witnessed by N	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped pled down BOP. Clean BANDONED - FINAL REPO Mike Stubblefield w/O	om 2186' to sub- casing). POOH of 20-1070' (in 5- 2 cement from 4- 10 sacks Class ned location. ORT. Plugging OCD - Artesia.	Clerk
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 POOH with tubing. Nipp marker. PLUGGED AND Al Plugging witnessed by N I hereby certify that the information above is true SKONATURE	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped pled down BOP. Clean BANDONED - FINAL REPO Mike Stubblefield w/O	om 2186' to sub- casing). POOH of 20-1070' (in 5- 2 cement from 4- 10 sacks Class ned location. ORT. Plugging OCD - Artesia.	. Fin with tub hgrann ragged rface. Mixed and pumped 10 sacks with tubing to 1320'. Mixed 1/2" casing i food with tubing 43-193' (in 5-1/2" casing). C Gament From '50 Foo surface. Installed regulation abandonment completed 6-16-95. NOTE:
TIH w/5-1/2" CIBP and s CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 POOH with tubing. Nipp marker. PLUGGED AND Al Plugging witnessed by N I hereby certify that the information above is true SKONATURE Work Rusty Klein TYPE OR PRINT NAME (This space for State Use)	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped pled down BOP. Clean BANDONED - FINAL REPO Mike Stubblefield w/O	om 2186' to sub- casing). POOH of 20-1070' (in 5- 2 cement from 4- 10 sacks Class ned location. ORT. Plugging OCD - Artesia.	Clerk
TIH w/5-1/2" CIBP and es CIBP at 2186'. Spotted Class C cement from 218 and pumped 30 sacks Cla to 443'. Mixed and pur POOH with tubing to 50 POOH with tubing. Nipp marker. PLUGGED AND AI Plugging witnessed by N I hereby certify that the information above is true skinature with the information above is true TYPE OR PRINT NAME Rusty Klein	d 52 bbls plug mud fr 86-2086' (in 5-1/2" c ass C cement from 132 mped 30 sacks Class C '. Mixed and pumped pled down BOP. Clean BANDONED - FINAL REPO Mike Stubblefield w/O	om 2186' to su asing). POOH 20-1070' (in 5- 2 cement from 4- 10 sacks Class ned location. ORT. Plugging OCD - Artesia.	Clerk DATE June 27, 1995 Clerk DATE JUNE 27, 1995 Clerk DATE JUNE 27, 1995

. .

to Appropriate District Office	Energy, Minerals and Natural Res	sources Department	Revised 1-1-89
DISTRICT I	OIL CONSERVATIO	N DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088 Santa Fe, New Mexico 87504-2088		30-015-22045
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No. L-4954
SUNDRY NOT	TICES AND REPORTS ON WEL	LS	
(DO NOT USE THIS FORM FOR PR DIFFERENT RESE (FORM C	COPOSALS TO DRILL OR TO DEEPEN (ERVOIR. USE "APPLICATION FOR PER C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
Type of Well: OIL GAS WELL WELL] OTHER		Four Dinkus GV State
2. Name of Operator			8. Well No.
YATES PETROLEUM CORPOR 3. Address of Operator	KAIIUN		9. Pool name or Wildcat
105 South 4th St., Ar	tesia, NM 88210		Wildcat Glorieta Yeso
4. Well Location Unit Letter0 :66	60 Feet From The South		_
Section 16	Township 18S Ran 1////////////////////////////////////	nge <u>25E</u> DF. RKB. RT. GR. etc.)	NMPM Eddy County
	10. Elevation (Show whether 1 3551'		
11. Check	Appropriate Box to Indicate N		leport, or Other Data
	ITENTION TO:	SUE	SEQUENT REPORT OF
		REMEDIAL WORK	
	CHANGE PLANS	COMMENCE DRILLIN	
	ليبيها	CASING TEST AND C	
DTHER:		OTHER:	[
12. Describe Proposed or Completed Ope work) SEE RULE 1103.	rations (Clearly state all pertinent details, an	nd give pertinent dates, inclu	uding estimated date of starting any proposed
	Crith 1/OCD - Artodic		- · · · · ·
in and rigged up pull Nippled up BOP. POOR TIH w/5-1/2" CIBP and CIBP at 2186'. Spot Class C cement from 2 and pumped 30 sacks (to 443'. Mixed and p POOH with tubing to 2 POOH with tubing. N marker. PLUGGED AND	ling unit. Nippled down H with tubing, perforate d set at 2186'. Rigged ted 52 bbls plug mud fro 2186-2086' (in 5-1/2" ca Class C cement from 1320 pumped 30 sacks Class C 50'. Mixed and pumped J ippled down BOP. Cleane	n pumping unit. ed sub and mud down wireline. om 2186' to sur asing). POOH w D-1070' (in 5-1 cement from 44 10 sacks Class ed location. I RT. Plugging c	plugging operations. Moved POOH with rods and pump. anchor. Rigged up wireline. TIM The tubing pand tagged face; Mixed and pumped 10 sacks ith tubing to 1320'. Mixed /2" casing). POOH with tubing 3-193' (in 5-1/2" casing). C cement from 50' to surface. installed regulation abandonment ompleted 6-16-95. NOTE:
in and rigged up pull Nippled up BOP. POOR TIH w/5-1/2" CIBP and CIBP at 2186'. Spot Class C cement from 2 and pumped 30 sacks (to 443'. Mixed and p POOH with tubing to 9 POOH with tubing. No marker. PLUGGED AND Plugging witnessed by	ling unit. Nippled down H with tubing, perforate d set at 2186'. Rigged ted 52 bbls plug mud fro 2186-2086' (in 5-1/2" ca Class C cement from 1320 pumped 30 sacks Class C 50'. Mixed and pumped 1 ippled down BOP. Cleane ABANDONED - FINAL REPOH y Mike Stubblefield w/00	n pumping unit. ed sub and mud down wireline. om 2186' to sur asing). POOH w D-1070' (in 5-1 cement from 44 10 sacks Class ed location. I <u>RT.</u> Plugging c CD - Artesia.	POOH with rods and pump. anchor. Rigged up wireline. TIN The tubing pud tagged face wire and pumped 10 sacks ith tubing to 1320'. Mixed /2" casing), POOH with tubing 3-193' (in 5-1/2" casing). C cement from 50' to surface. installed regulation abandonment
in and rigged up pull Nippled up BOP. POOR TIH w/5-1/2" CIBP and CIBP at 2186'. Spot Class C cement from 2 and pumped 30 sacks (to 443'. Mixed and p POOH with tubing to POOH with tubing. N marker. <u>PLUGGED AND</u> Plugging witnessed by I hereby certify that the information above is	ling unit. Nippled down H with tubing, perforate d set at 2186'. Rigged ted 52 bbls plug mud fro 2186-2086' (in 5-1/2" ca Class C cement from 1320 pumped 30 sacks Class C 50'. Mixed and pumped J ippled down BOP. Cleane ABANDONED - FINAL REPOH y Mike Stubblefield w/00	n pumping unit. ed sub and mud down wireline. om 2186' to sur asing). POOH w D-1070' (in 5-1 cement from 44 10 sacks Class ed location. I <u>RT.</u> Plugging c CD - Artesia.	POOH with rods and pump. anchor. Rigged up wireline. TIN The tubing pud tagged face wire and pumped 10 sacks ith tubing to 1320'. Mixed /2" casing), POOH with tubing 3-193' (in 5-1/2" casing). C cement from 50' to surface. installed regulation abandonment
in and rigged up pull Nippled up BOP. POOR TIH w/5-1/2" CIBP and CIBP at 2186'. Spot Class C cement from 2 and pumped 30 sacks (to 443'. Mixed and p POOH with tubing to 9 POOH with tubing. No marker. PLUGGED AND Plugging witnessed by	ling unit. Nippled down H with tubing, perforate d set at 2186'. Rigged ted 52 bbls plug mud fro 2186-2086' (in 5-1/2" ca Class C cement from 1320 pumped 30 sacks Class C 50'. Mixed and pumped J ippled down BOP. Cleane ABANDONED - FINAL REPOH y Mike Stubblefield w/00	n pumping unit. ed sub and mud down wireline. om 2186' to sur asing). POOH w D-1070' (in 5-1 cement from 44 10 sacks Class ed location. I <u>RT.</u> Plugging c CD - Artesia.	POOH with rods and pump. anchor. Rigged up wireline. TIM Ith tubing / And tagged face, Mixed and pumped 10 sacks ith tubing to 1320'. Mixed /2" casing), POOH with tubing 3-193' (in 5-1/2" casing). C cement from 50' to surface. installed regulation abandonment completed 6-16-95. NOTE:
in and rigged up pull Nippled up BOP. POOR TIH w/5-1/2" CIBP and CIBP at 2186'. Spot Class C cement from 2 and pumped 30 sacks (to 443'. Mixed and p POOH with tubing to POOH with tubing. No marker. PLUGGED AND Plugging witnessed by Ihereby certify that the information above is SKONATURE	ling unit. Nippled down H with tubing, perforate d set at 2186'. Rigged ted 52 bbls plug mud fro 2186-2086' (in 5-1/2" ca Class C cement from 1320 pumped 30 sacks Class C 50'. Mixed and pumped J ippled down BOP. Cleane ABANDONED - FINAL REPOH y Mike Stubblefield w/00	n pumping unit. ed sub and mud down wireline. om 2186' to sur asing). POOH w D-1070' (in 5-1 cement from 44 10 sacks Class ed location. I <u>RT.</u> Plugging c CD - Artesia.	POOH with rods and pump. anchor. Rigged up wireline. TIM ich tubing pand tagged face, Mixed and pumped 10 sacks ith tubing to 1320'. Mixed /2" casing), POOH with tubing 3-193' (in 5-1/2" casing). C cement from 50' to surface. nstalled regulation abandonment ompleted 6-16-95. NOTE: Clerk DATE June 27, 1995

.