

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-015-22051

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-8814-12

7. Lease Name or Unit Agreement Name
EMPIRE ABO UNIT "K"

8. Well No.
141

9. Pool name or Wildcat
EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator BP America Production Company
3. Address of Operator P.O. Box 1089, Eunice, NM 88231	4. Well Location Unit Letter <u>K</u> : <u>1370</u> Feet From The <u>S</u> Line and <u>2445</u> Feet From The <u>W</u> Line
Section <u>2</u> Township <u>18S</u> Range <u>27E</u> NMPM <u>EDDY</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3521' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Workover ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6203' PBD: 6155' PERFS: 5880-5951' (old), 5716-5850' (new)
07.15.02: MIRUPU. Unhang well. POH w/rods & pmp.
07.16.02: Bled well down. Pmp 40 bbls to hot oil tbq. NDWH. NUBOP. POH w/tbg.
07.17.02: RIH w/bit & scraper. Test tbq in hole.
07.18.02: Perf 2 JSPF 5716-40', 5788-5829', 5844-50'. RIH w/BP and pkr. Set BP @ 5868'.
07.19.02: RU & pmp 500 gals 7% HCL acid to pickle tbq. Wait 30 mins. swab back acid. Fish SV. spot 3 bbls 15% HCL NEFE. Pull up and set pkr @ 5602'. Pmp 3550 gals 15% HCL NEFE running 225 ball sealers.
07.22.02: Bled well down. Unset pkr. RIH 9 jts. Unset BP. POH. RIH w/bit. Tag @ 5918'. CO to 5970'. POH.
07.24.02: RIH w/prod. assy. Set 2-3/8" tbq @ 5909'. SN @ 5913'. RTP. In 24 hrs pmp 4 bo, 2 bw, 40 mcf.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Administrative Assistant DATE 08.29.02

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505.394.1649

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

SEP 16 2002

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: