

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Er. , Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 198C, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

NOV 29 '90

WELL API NO. 30-015-21471
5. Indicate Type of Lease
STATE ☒ FEE ☐
6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Spencer Com.
8. Well No.
1
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Mewbourne Oil Company

3. Address of Operator
P.O. Box 5270 Hobbs, New Mexico 88241

4. Well Location
Unit Letter F : 1650 Feet From The West Line and 1650 Feet From The North Line

Section F Township 18S Range 26E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3377' G.L.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐
SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

A minimum of 9.0#/gal. plug mud will be used to displace hole. Set CIBP in 4 1/2" casing @ 8850' and spot 10 sx. cement on top of plug. Spot 35 sx. plug in 4 1/2" casing across ~~Wolfcamp~~ formation at ~~7400-7500~~. Attempt to cut off 4 1/2" casing at ±4300' (Abo form.). Spot 50 sx. in/out of cut-off and tag cement. Spot 50 sx. plug in hole across the Glorieta formation at ~~3100-3200~~. Spot 50' in/out plug across 8 5/8" shoe at 1960' and tag cement. Spot 100' plug at 1300-1400' in 8 5/8" casing. Spot 50' plug at surface.

Plugging

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE W H Cravey TITLE District Supt. DATE 11/27/90
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)
APPROVED BY David M. ... TITLE Geologist DATE 12/14/90
CONDITIONS OF APPROVAL, IF ANY:

As per ... 100' ...