1				. It
Submit 3 Copies to Appropriate District Office	State of New Energy, Minerals and Natura	Mexico Il Resources Department	lar 191 <b>991</b>	Form C-103 C
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION		WELL APING	·	
DISTRICT II Santa Fe. New Mexic			30-025-2	
P.O. Drawer DD, Artesia, NM 88210		5. Indicate Type of Lease STATE FEE X		
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas	i Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lesse Name or SPENCER	Unit Agreement Name COM
1. Type of Well: OIL OAS WELL X	OTHER			
2. Name of Operator			8. Well No.	
Mewbourne Oil Company 3. Address of Operator			9. Pool name or V	Vildçe
P. O. Box 7698, Ty 4. Well Location	<u>vler, Texas 75711</u>		Htopa	Pann
Unit LetterF :165	50 Feet From The Wes	t Line and 16	50 Feet From	The <u>North</u> Line
Section 9	Township 185	Range 26E	NMPM	Eddy County
	10. Elevation (Show whe	<pre>sther DF, RKB, RT, GR, etc.) 3377' GL</pre>		
11. Check	Appropriate Box to Indica		eport, or Other	Data
NOTICE OF INT	ENTION TO:	SUE	SEQUENT R	EPORT OF:
	CHANGE PLANS		G OPNS.	
PULL OR ALTER CASING		CASING TEST AND C		
OTHER:				
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
4/13/91 - Ran in hole with CIBP and set at 8500'. Loaded hole with 9.0#/gal plug mud and spotted 10 sacks of cement on top of bridge plug. Broke down wellhead and prepared to weld on th casing.				
4/16/91 - Welded on to c	asing. Shot casing	at 4300'. Shot a	gain at 4000	•. Installed jacks.
4/17/91 - Rigged up casing jacks. Pulled and laid down casing at 638'/ Rigged down casing jacks and ran in hole with tubing. Spotted plug at 7070' with 25 sacks. Pulled up to 5560' and spotted 25 sacks. Pulled up to 2315'.				
4/18/91 - Pulled out with tubing. Pressured to 500#. Held OK. Ran tubing to 2215'. Spotted 50 sack plug and pulled tubing. Ran wireline and perforated at 1300'. Pulled out of hole and pressured up to 500#. Held OK. Ran tubing and spotted plug over perfs.				
4/19/91 - Spotted 50 sac Job complete.	k plug at surface.	Cut off wellhead.	Installed	dry hole marker. Post IP-2 4-14-91
I hereby certify that the information above is true	$ \rightarrow                                   $			P& H
SIGNATURE Varford		Engr.Oprns.	Secretary	<u>DATE</u> <u>5/24/91</u> (903) 561-2900
TYPE OR PRINT NAME OUT DOT THOMPSON D				
(This space for State Use)	Religian	times 2016 Bell	SPECTON	- DATE 2-5/-92
		11fLE		DATE - 1