

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-22140
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	K-6973
7. Lease Name or Unit Agreement Name	
West 4-Dinkus "HZ" State	
8. Well No.	1
9. Pool name or Wildcat	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P & A <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	4. Well Location Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line Section 22 Township 18S Range 24E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3750' KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in and rigged up pulling unit. Release packer and RBP and TOOH. WBIH w/retrieving tool to get packer with standing valve at 7500'. Could not get below 1000'. Believe casing is parted. TOOH w/retrieving tool and TIH w/muleshoe. Tagged packer at 7476'. Consulted with Ray Smith, OCD - Artesia, and obtained approval to revise P & A procedure as follows: spot 170 sacks Class "C" Neat from 7476-4900'. WOC. Tagged plug at 5240'. Topped off plug with 25 sacks Class "C" 2% CaCl2. WOC. Tagged plug at 4860'. Spotted 60 barrels plugging mud from 4860-1000'. Pulled tubing up to 3700'. Perforated top of Abo at 3900' with 4 shots with thru tubing strip gun. TIH w/tubing to 3900'. Spot 25 sacks Class "C". Pull tubing up to 1700'. Perforate top of Glorieta at 1845' with 4 shots with thru tubing strip gun. Lowered tubing to 1845' and pumped 25 sacks Class "C". Pull tubing. Welded on 4-1/2" pull nipple. Casing was parted as expected. Pulled and laid down 30 joints of 4-1/2" casing (1000'). TBIH with 2-3/8" tubing. Tagged casing stub. Worked tubing back down into casing to 1050'. Ran weight bar on wireline thru tubing. Tagged Glorieta plug at 1604' to verify that Glorieta plug had balanced thru perfs to put cement

CONTINUED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Feb 24, 1994

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY Mike S. [Signature] TITLE Field Rep. I DATE May 23, 94

CONDITIONS OF APPROVAL, IF ANY: