

1850-1851

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-0487738

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

RIO COMM.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

PENASCO DRAW MORROW

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SEC. 29, T-18S, R-25E

12. COUNTY OR PARISH 13. STATE

EDDY

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. NAME OF OPERATOR
BRAVO OPERATING CO.
3. ADDRESS OF OPERATOR
P. O. BOX 2160, HOBBS, NM 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
1980' FNL & 1980' FEL

RECEIVED

FEB -1 '90

ARTESIA, OFFICE

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3581 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) PLUG & ABANDON

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- (1) MOVE IN & RIG UP. SET 5½" CIBP @ 8650'. CAP W/ 4 SKS. OF CEMENT.
- (2) LOAD HOLE WITH MUD.
- (3) CUT 5½" CSG. @ 6161'. LAY DOWN CASING.
- (4) SPOT 50 SK. CEMENT PLUG @ 5½" STUB @ 6261'. WOC. TAG PLUG @ 6085'.
- (5) SPOT 35 SK. CEMENT PLUG @ 5274'. WOC. TAG PLUG @ 5160'.
- (6) SPOT 35 SK. CEMENT PLUG @ 4157'.
- (7) SPOT 35 SK. CEMENT PLUG @ 2104'.
- (8) SPOT 80 SK. CEMENT PLUG @ 1300'. WOC. TAG PLUG @ 1050'.
- (9) SPOT 30 SK. CEMENT PLUG @ 350'.
- (10) SPOT 15 SK. CEMENT PLUG @ SURFACE. INSTALL P & A MARKER.

RECEIVED
JAN 15 11 20 AM '90
OAS
ARE

18. I hereby certify that the foregoing is true and correct

SIGNED Raymond M. Weldenadok/H

TITLE P & A SUPERVISOR, BABER

DATE 1-18-90

(This space for Federal or State office use)

Orig. Signed by Adam Salameh

APPROVED BY

TITLE PETROLEUM ENGINEER

DATE 1-29-90

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side