	- NIMOC	C POPY				ogento SF	
Form 9-331 (May 1963)	DEPART	ULLED STATES		BMIT IN TRIPLACA' ther instructions on seslde)	re- 5. LEAS	Form approved. Budget Bureau No. 42-R1 E DESIGNATION AND SERIAL	
		· · · · · · · · · · · · · · · · · · ·				1–A–3302 NDIAN, ALLOTTEE OR TRIBE N.	AME
		osals to drill or to deepen CATION FOR PERMIT-" for					
1. OIL GAS WELL WELL	X OTHER	d			7. UNIT	AGREEMENT NAME	
 NAME OF OPERATOR M. Brad Bennett, Inc. Robert K. Hillin ADDRESS OF OPERATOR 						8. FARM OR LEASE NAME King-Federal 9. WELL NO.	
At surface 990'	FSL &	2310' FEL	DEC	20 1977	11. SEC	LIdcat Monour	
14. PERMIT NO.		15. ELEVATIONS (Show w	hether DF, RT, GR,	, C. C .		5-T-18-S R-2	3-E
			L.	SIA, OFFICE	Eddy		Mexic
16.	Charle A	Appropriate Box To Ind		(N-4:- D 4			
N	OTICE OF INTE		icale indiure o				
		F			SEQUENT REPO		
TEST WATER SHUT-OFF FRACTURE TREAT	B.	PULL OR ALTER CASING MULTIPLE COMPLETE		ATER SHUT-OFF Acture treatment		REPAIRING WELL	
SHOOT OR ACIDIZE			7	HOOTING OR ACIDIZING		ABANDON MENT*	
REPAIR WELL		CHANGE PLANS		Other)			
(Other)						ple completion on Well	
1 • • • • • • • • • • • • • • • • • •				Completion or Rece	ompletion Rep	ort and Log form.)	
nent to this work.)*	ephone	conversation	with Mr.	Completion or Reco and give pertinent da measured and true ve Knolph peri	ompletion Rep ites, including rtical depths	ort and Log form.) g estimated date of starting for all markers and zones p	any erti-
rsuant to tel requested to 50 s 35 s 35 s 40 s	ephone Plug a x plug x plug x plug x plug x plug	Lionally urined, give subsuri	with Mr. s follows 530' 000' 120' 150'	Completion or Reco and give pertinent da measured and true ve Knolph per:	mpletion Rep ites, including rtical depths	ort and Log form.) g estimated date of starting for all markers and zones p	any ærti-
requested to 50 s 35 s 40 s 10 s	ephone Plug a x plug x plug x plug x plug x plug x plug	conversation and Abandon as from 6680'-65 from 5100'-50 from 3520'-34 from 1550'-14	with Mr. s follows 530' 000' 120' 150' Eace	Completion or Reco and give pertinent da measured and true ve Knolph per:	mpletion Rep tres, including rtical depths missior	ort and Log form.) g estimated date of starting for all markers and zones p	erti-
Irsuant to tel requested to 50 s 35 s 35 s 40 s 10 s dry hole marke	ephone Plug a x plug x plug x plug x plug x plug er will	conversation and Abandon as from 6680'-65 from 5100'-50 from 3520'-34 from 1550'-14 from 25'-surf	with Mr. s follows 30' 000' 120' 150' Eace	Completion or Reco and give pertinent da measured and true ve Knolph per:	REC N.S.	SURVED NOT and Log form.) s estimated date of starting for all markers and zones p N EIVED 1 1 1 1 1 1 1 1 1 1 1 1 1	
requested to 50 s 35 s 40 s 10 s	ephone Plug a x plug x plug x plug x plug x plug er will	conversation and Abandon as from 6680'-65 from 5100'-50 from 3520'-34 from 1550'-14 from 25'-surf l be installed	with Mr. s follows 30' 000' 120' 150' Eace	Completion or Reco and give pertinent da measured and true ve Knolph per:	REC N.S.	port and Log form.) g estimated date of starting for all markers and zones p 1	

*See Instructions on Reverse Side