Drawer DD	
Form 3160-5 November 1983) UN: (ED STATES **RESIGN, NM 8827-0417 IN TRIPL. ATE.	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985
RECEIVED BY DEPARTMENT OF THE INTERIOR CONTROL OF THE INTERIOR OF THE PROPERTY OF THE INTERIOR	5. LEASE DESIGNATION AND SERIAL NO. LC - 0654781- h
JAN 18 SUBSDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Use "Al PLICATION FOR PERMIT—" for such proposals.) 1. O. C. D.	7. UNIT AGREEMENT NAME
WEART ALA STEFICE	S. FARM OR LEASE NAME
amoco Production Company	Fideral F
P.O. Box 68, Hobles, nrn 88240	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL OF WALDCAT
1980'FNLX 1650'FEL, Section 3	11. SEC., T., R., M., ORALK. AND SURVEY OR AREA
(Unit G,SW/4, NE/4)	3-18-27
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3560. GL	12. COUNTY OR PARISH 13. STATE
16. Check Appropriate Box To Indicate Nature of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO:	JENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	REPAIRING WELL ALTERING CABING
BHOOT OR ACIDIZE ABANDON BHOOTING OR ACIDIZING	ABANDONMENT*
(Other) CHANGE PLANS (Other) (Other) (Other)	of multiple completion on Well letion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, proposed work. If well is directionally drilled, give subsurface locations and measured and true vertice nent to this work.)	including estimated date of starting any
MISU 12-26-84. Han before-treatment survey. acide	il with 3000 gala.
15% NEFE HCL gelled acid 7200'- 6900'. Hanf after-the	realment survey.
Risel skr. at 17125 and acidized with 1000 gala. 1	5% NEFE HOR.
Pullet they and sould 66 13-66 622', 6814'- 6818', 6	1947'-6952" and
7006-7014! Wan Vretrievable bridge slug and set	
at 6850. acid with 2000 gala /150% acid. E	- A
budge plug at 68 48 and stepher at 6500! a	cederal with 2000
gald. (15%) acid. Raw production equipment. m	108U 1-1-85.
Began zomp toting. Show 24 hrs. zompd 3 BO	X 83 BW X 110 MCF.
Thell to corrently producing.	
	•
0 0	
0+6-BLM, C 1-JRB 1-FJN 1-GCC 18. 1 hereby certify that the foregoing is graye and correct	
SIGNED BONETA Coble Tildoninistrative and	hptor 1-11-85
(This space for Federal or State office use) ACCEPTED FOR RECORD	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY : (-)	DATE
JAN 17 1955	

*See Instructions on Reverse Side