C151

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No. NM-23417

SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allotte or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir Use "APPLICATION FOR PERMIT-" for such proposals SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreement Designation 1. Type of Well Gas Well Other X Oil Well 8. Well Name and No. 2. Name of Operator TRAVIS DEEP UNIT # 3 Harvey E. Yates Company 9. API Well No. 30-015-22355 3. Address and Telephone No. P.O. Box 1993, Roswell, NM 88202 1-505-623-6601 Field and Pool, or Exploratory Area TRAVIS UPPER PENN 11. County or Parish, State 4. Location of Well (Footage, Sec., T., R., M, or Survey Description) EDDY CO., NM B. 1980' FEL & 660' FNL SEC. 13, T-18S, R-28E CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Change in Plans Abandonment X Notice of Intent New Construction Recompletion Non-Routine Fracturing Plugging Back Subsequent Report Water Shut-Off Casing Repair Conversion to Injection Altering Casine Final Abandomen Dispose Water X Other Completion or Recompletion Report and Log Form.) 13. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) CORRECT NAME FOR THIS WELL IS AS STATED ABOVE NOT TRAVIS PENN # 2 AS INC INDICATED. **CURRENT PERFS: 9311-9704' (OA)** UNSET UNI V PKR & LOWER 12 JTS TO LOK-SET PKR. UNSET & POOH. GIH & SET 5 1/2" CIBP @ 9300' w/ 50' CMT. PULL TBG TO 8160' & SPOT 100' PLUG. (TOP OF WOLFCAMP) PULL TBG TO 6200' & SPOT 100' PLUG. POOH. (TOC @ 5320') CUT & PULL 5 1/2" @ 5000' +/-. LD CSG. GIH w/ TBG. RUN TBG 50' INSIDE STUB & PUMP 25 SK PLUG (100' PLUG). (TAG) PULL TBG TO 2950' & PUMP 25 SK PLUG ACROSS SHOE. (TAG) PULL TBG TO 1000' & PUMP 100' PLUG. PULL TBG TO 400' & PUMP 100' PLUG. PULL TBG TO 50' & PUMP 10 SK SURFACE PLUG. INSTALL DRY HOLE MARKER. BACK FILL PIT, CUT OFF ANCHORS, CLEAN LOCATION. CALL BLM 24 HOURS PRIOR TO COMMENCEMENT 14. I hereby certify that the foregoing true and correct 6/5/98 PROD. MGR./ ENG. Date RAY F. NOKES (This space for Federal or State office use) Approved by Conditions of approval, if any: ROSWELL RUSOURCE AREA This 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent states or representations as to any matter within its jurisdiction.