

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

clsf  
Op

OIL CONSERVATION DIVISION

DISTRICT I  
P. O. Box 1980 Hobbs, NM 88240  
  
DISTRICT II  
P. O. Drawer DD, Artesia, NM 88210  
  
DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

P. O. Box 2088  
Santa Fe, New Mexico 87504-2088

Well API NO.	30-015-22369
5. Indicate Type or Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	LOCO HILLS WELCH
8. Well No.	# 1
9. Pool name or Wildcat	LOCO HILLS BONE SPRING

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Harvey E. Yates Company
3. Address of Operator P.O. Box 1933, Roswell, NM 88202 1-505-623-6601	4. Well Location Unit Letter <u>D</u> : <u>480</u> Feet From The <u>NORTH</u> Line and <u>500</u> Feet From The <u>WEST</u> Line Section <u>9</u> Township <u>18S</u> Range <u>29E</u> NMPM <u>EDDY</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3516' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

NOTIFY OCD II -ARTESIA 24 HOURS PRIOR TO COMMENCEMENT  
SET CIBP @ 6175' PLUS 35' CMT.  
FREE POINT CSG & CUT (EST. 5500' REC.)  
POOH LAYING DOWN CASING.  
100' PLUG (50' IN & OUT) @ CUT STUB @ APPROX. 5500' ——— Tag  
100' PLUG @ 2950' ——— Tag  
100' PLUG @ 450' ——— Tag  
CUT OFF WH  
PUMP 50' SURFACE PLUG  
INSTALL DRY HOLE MARKER.  
BACKFILL PIT & CLEAN LOCATION.  
ARTESIA OCD II 1-505-748-1283

RECEIVED

MAY - 6 1997

Notify N.M.O.C.C. in sufficient time to witness

Tag

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE RAY F. NOKES	TITLE PROD. MGR. / ENGINEER	Date 4/22/97
TYPE OR PRINT NAME RAY F. NOKES		TELEPHONE NO. 1-505-623-6601

(This space for State use) Approved by Conditions of approval, if any:	Title District Supervisor	Date 5-9-97
--	------------------------------	----------------