			•		copy	10 01	
Form 9-331 (May 1963)	DEPAF	UNI D STATES RTMENT OF THE INT	SUBMIT IN TRIPL (Other Instructions . ERIOR verse side)	10• re- 5. LE	Form approv Budget Bure SE DESIGNATION	au No. 42-R1424.	
		GEOLOGICAL SURVEY		N	NM 0487738		
(Do not use th	NDRY NO	OTICES AND REPOR opposals to drill or to deepen or t LICATION FOR PERMIT—" for s	tor back to a different reservoir.	6. 15	INDIAN, ALLOTTE	E OR TRIBE NAME	
1. OIL GAS WELL WELL	L XXC OTHE	R	MAR 2 2 1978 MAR 2 2 1978 U.S. GEULUGINAL SURVEY	7. UN	7. UNIT AGREEMENT NAME		
					8. FARM OR LEASE NAME		
2. NAME OF OPERATOR Yates Petroleum Corporation U.S. GruLUGUAL SUND 3. Address of Operator ARTESIA, NEW MEXICO					Federal "AB"		
3. ADDRESS OF OPERATOR					9. WELL NO.		
207 South 4th Street - Artesia, NM 88210					5		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 660' FWL of Section 21-185-25E RECEIVE 660' FWL of Section 21-185-25E					10. FIELD AND POOL, OR WILDCAT		
					Und. Morrow		
					11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21-18S-25E Unit L NMPM		
14. PERMIT NO.	1978	15. ELEVATIONS (Show whet	her DF, RT, GR, etc.)	12. C	DUNTY OR PARISI		
APR 5	1370	35	61' GR		Eddy	NM	
	C. C.Check	Appropriate Box To Indico	ate Nature of Notice, Report,	or Other E			
TEST WATER SHU	T-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	X	REPAIRING	WELL	
FRACTURE TREAT		MULTIPLE COMPLETE	FRACTURE TREATMENT		ALTERING C	ASING	
SHOOT OR ACIDIZE		ABANDON*	SHOOTING OR ACIDIZIN	G	ABANDONME	NT*	
REPAIR WELL		CHANGE PLANS	(Other) Spud			×	
			(Note: Report 1	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

Spudded a 17½" hole at 9:00 AM 3-11-78. Ran 7 joints of 13-3/8" 48# K-55 casing (346') set at 335'. 1-Baffle Plate, centralizer at 263'. Cemented w/370 sacks of Class C 4% CaCl. Cement did not circulate. PD 11:45 PM 3-11-78. Slurry wt. 14.8, 1.32 cu ft/sx. Compressive Strength at 70 deg 1023 psi in 12 hours. WOC 12 hours and started to drill plug - no cement around bottom of casing. Spotted 150 sacks of Class C 4% CaCl on bottom. WOC 12 hours, reduced hole and drilled plug, tested to 600#. OK and resumed drilling.

TD 1100' - Ran 25 joints of 8-5/8" 24# K-55 casing (1106') set at 1100'. 1-Guide shoe at 1100'. Insert float at 1060'. Centralizers and baskets at 1000 and 500'. Cemented as follows: 150 sacks of RFC-2 2% CaCl. 515 sacks 50/50 poz, 10#/sx Kolite, 1/4# celoflake 2% CaCl, 150 sacks Class C 2% CaCl. PD 10:30 AM 3-14-78. Cement did not circulate. Ran Temp Survey and found top of cement at 282'. Ran 1" and spotted 100 sacks of Class C 4% CaCl. WOC 3 hours and ran 1", tagged top of cement at 50', spotted 125 sacks of Class C 4% CaCl. Cement circulated. PD 9:30 PM 3-14-78. WOC 18 hours, NU, tested BOP's to 1500#. OK, reduced hole to 7-7/8", drilled plug and tested to 600#. OK. Resumed drilling.

18. I hereby certify that the foregoing is true and correct SIGNED <u>fustive to Mluce</u>	TITLE Geol. Secty	DATE 3-21-78
(This space for Federal or State offic use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	ACTING DISTRICT ENGINEER	DATE APR 4 - 1978

*See Instructions on Reverse Side