

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
FEB 27 1980

3a. Indicate Type of Lease State ☒ Fee ☐	
3. State Oil & Gas Lease No. L-889	
7. Unit Agreement Name	
8. Farm or Lease Name State "32" Com	
9. Well No. 1	
10. Field and Pool, or Wildcat Wildcat	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS. O. C. D.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER ☐

1. Name of Operator
MADDOX ENERGY CORPORATION

2. Address of Operator
The Blanks Building, Suite 906, Midland, Texas 79701

3. Location of Well
UNIT LTYTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE East LINE, SECTION 32 TOWNSHIP 18-S RANGE 24-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3758' KB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WELL DATA - Casing and Cement

13 3/8" set at ³⁵³450' with 400 sx cmt - circulated
8 5/8" set at 2012' with 1150 sx cmt - circulated
4 1/2" set at 8565' with 450 sx cmt - ~~circulated~~
Cemented through perfs at 6630' with 200 sx Class "H" - est TOC at 5500'.

Perforations

8392'-8510'; 8184'-8190'; 7416'-7422'; 6588'-6596'

Plugs

CIBP at 8300' with 35' cmt.
CIBP at 7560' with 40' cmt.
CIBP at 7320' with 40' cmt.

(OVER)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Operations Manager DATE 25 February 1980

APPROVED BY [Signature] TITLE SUPERVISOR DATE FEB 28 1980

CONDITIONS OF APPROVAL, IF ANY:

* as noted

Notify N.M.O.C.C. in sufficient time to allow

Plugging

(Continued)

Proposed Plugging Procedure

1. Set cast iron bridge plug at 6550' and cap with 40' cement with
dump bailer.

2. Cut and pull 4 1/2" casing from 5500' or from free-point.

3. Spot 40 sack cement plugs at 4 1/2" stub, 4000', 3200', 2050', and 300'.
* 400' Hole to be loaded with 10#/gal mud laden fluid.

4. Set 10 sack cement plug at surface with dry hole marker.