STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTME	ENT			
	OIL CONSERVATION DIVIS			
DISTRIBUTION	Р. О. ВЬ			Form C-103
SANTA FE		MEXICO 8750	- 1000	Revised 10-1-78
FILE	SANTA LE, NEM	MEXICO 8/JUN	6 1980	
U.S.O.S.				Sa. Indicate Type of Lease
LAND OFFICE		0.1	C. D.	State X Fee
OPERATOR]	ARTESIA	, OFFICE	5. State Oil & Gas Lease No.
	-			L-889
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DECEDEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT				
1.				7. Unit Agreement Name
OIL GAS WELL	OTHER-			
2. Name of Operator			· · · · · · · · · · · · · · · · · · ·	8, Farm or Leuse Name
MADDOX_ENERGY_CORPORATION			State "32" Com	
3. Address of Operator			9. Well No.	
The Blanks Building, Suite 906, Midland, Texas 79701			1	
4. Location of Well			10. Field and Pool, or Wildcat	
UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM				Wildcat
East	32 18-	-S 24–E		
THE East LINE, SECTION YOWNSHIP RANGE 24-E				
11111111111111111111111111111111111111			12. County	
;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;			Eddy	
Check	Appropriate Box To Indicate N	ature of Notice, Re	port or Oth	er Data
NOTICE OF IN	TENTION TO:	SU	BSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPHS		PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT		
		OTHER		[]
OTHER	······································	•		
17. Describe Proposed or Completed Op	erations (Clearly state all pertinent deta	ils, and give pertinent dat	es. including	stimated date of starting any proposed

work) SEE RULE 1103.

SEE ATTACHED REPORT

16. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

and ante longles

TITLE Production Supervisor

DATE June 3, 1980

CONDITIONS OF APPROVAL, IF ANY:

MADDOX ENERGY CORPORATION STATE "32" NO. 1 EDDY COUNTY, NEW MEXICO

- 5-06-80 Rigged up Baber Well Service unit. Removed wellhead. Released packer. TOH w/tubing and packer.
- 5-07-80 Rigged up wire line truck. Set 4 1/2" CIBP at 6550'. Dumped 40' cement on top of bridge plug w/dump bailer. Ran tubing to 6450'. Loaded hole w/10# mud. TOH w/tubing. Removed 4 1/2" wellhead.
- 5-08-80 Ran wire line cutting tool to 5458' and cut 4 1/2" casing. Pulled 168 jts 4 1/2" casing. Ran tubing to 2000'.
- 5-09-80 Finished running tubing to 5518'. Spotted 40 sacks cement. Pulled 30 stands. WOC 3 1/2 hrs. Tagged cement at 5373'. Layed tubing down to 4000'. Spotted 40 sacks cement. Spotted 40 sacks cement at 3200'. Spotted 40 sacks cement at 2050'. Pulled 25 stands of tubing. WOC.
- 5-10-80 Tagged top of cement at 1949'. Layed 2 3/8" down to 400'. Spotted 40 sacks cement. Layed down tubing. Removed 4 1/2" wellhead. Dug out cellar. Cut surface head off. Put 10 sacks of cement at surface.

Plugging operation completed.

Casing left in hole:

13 3/8" - surface to 353'
8 5/8" - surface to 2012'
4 1/2" - 5458' to 8565' (3107')

Perforations:

8392'-8510', 8184'-8190', 7416'-7422', 6588'-6596'

Plugs:

CIBP at 8300' w/35' cement CIBP at 7560' w/40' cement CIBP at 7320' w/40' cement