#2-Wright Fed. Com Hondo Drilling Company Ed Alscott Wright com. Well No. 1. Page 4

10. PLANS FOR RESTORATION OF THE SURFACE.

- A. After finishing drilling and/or completion operations, all equipment and other materials not needed for further operations will be removed. Pits will be filled and the location cleaned of all trash and junk to leave the wellsite in as aesthetically pleasing a condition as possible.
- B. Any unguarded pits containing fluids will be fienced until they have been filled.
- C. If the proposed well is non-productive, all rehabilitation and/or vegetation requirements of the Bureau of Land Management and the United States Geological Survey will be complied with and will be accomplished as expeditiously as possible. All pits will be filled and leveled within 90 days after abandonment.

11. OTHER INFORMATION.

- A. Topography: The proposed wellsite is located in an area of low, rolling hills.
- B. The topsoil at the wellsite is moderately soft sand and caliche.
- C. Flora and Fauma: The vegetation cover at the wellsite is moderately sparse, consisting primarily of prairie flowers, yucca, mesquite, grease wood, shinnery, and miscellaneous semi-desert plants, with relatively little grass. The only wildlife observed were snakes, lizards, and birds, but the area is typical of semi-arid desert land and it is likely that other typical wildlife, such as rabbits, coyotes, gophers, kangaroo rats, badgers, etc. inhabit the area.
- D. There are no ponds, lakes, streams or rivers within a one-mile radius of the wellsite.
- E. There are no houses or other buildings within a three-mile radius of the wellsite. The nearest windmill is located three miles southeast of the wellsite.
- F. The wellsite is on state surface with federally controlled minerals.
- G. There is no evidence of any archeological, historical or cultural sites in the area.

12. OPERATOR'S REPRESENTATIVE.

A. The field representatives responsible for assuring compliance with the approved surface use and operations are:

(1) Drilling: Tommy D. Richey
P. O. Box 2075
Hobbs, New Mexico 88240
Office: 505-393-7944
Home: 505-397-1589
Mobile: 505-397-3188