

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Badget Budget No. 001-10
Expire: August 1, 1985
LEASE REGISTRATION AND SERIAL
NM 056426 (was NM-0924)
INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or pack back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR Hondo Drilling Company ✓

3. ADDRESS OF OPERATOR P. O. Drawer 2516, Midland, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface 660' FSL and 1,980' FEL, Unit 0, Sec. 31, T-18-S, R-29-E

14. PERMIT NO 30-015-22549 15. ELEVATIONS (Specify whether DE, GR, or G) 3,398' GR

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME Alscott Federal

9. WELL NO 3

10. FIELD AND POOL OR WILDCAT North Turkey Track, Strawn

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 31, T-18-S, R-29-E

12. COUNTY OR PARISH 13. STATE Eddy New Mexico

RECEIVED

MAY 22 '89

O.C.D.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

3. SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SEPARATING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE FLAG

COMPLETION

(Other)

(Note: Report results of multiple completion on Well Completion or Re-completion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Identify section pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We propose to test the 2nd Bond Spring Sand, depth 7,536' to 7,651' in the next 30 days.

Pull 2 3/8" tubing and 5 1/2" Guiberson Production Packer out of hole.

→ Set CIBP @ ±10,000' and cap w/ 35' cmt.

Set 5 1/2" Halliburton Bridge Plug at 8,200' with 35' cement on top.

Perforate 4 squeeze holes at 8,000' and cement 5 1/2" casing with 650 sacks Halliburton "light" cement and 250 sacks 50/50 Pozmix cement. Perforate well from 7,536' to 7,651' and acidize well with 4,000 gallons of 15% Nefe Acid, swab well and test.

If production warrants, Sand Frac well with 100,000 gallons Halliburton Versagel, carrying 200,000 lbs. of 16-30 Ottawa Sand.

RECEIVED
MAY 11 11 03 AM '89

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

President

DATE May 10, 1989

(This space for Federal or State office use)

APPROVED BY

FOR

DATE

5-18-89

CONDITIONS OF APPROVAL, IF ANY

*See Instructions on Reverse Side