

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other, instructive on reverse side)

BLM Form 3160-5, 10-4-83
Expires August 31, 1985

NM-0924

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Hondo Drilling Company

3. ADDRESS OF OPERATOR
P. O. Drawer 2516, Midland, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
660' FSL and 1,980' FEL, Unit 0, Sec. 31,
T-18-S, R-29-E

14. PERMIT NO.
30-015-22549

15. ELEVATIONS (Show whether OF, BT, SK, etc.)
3,398' GR

O. C. D.
ARTESIA, OFFICE

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Alscott Federal

9. WELL NO.
#3

10. AND POOL OR WILDCAT
2nd Bone Springs

11. SEC., T., S., M., OR BLK. AND SURVEY OR AREA
Sec. 31, T-18-S, R-29-E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other)

SUBSEQUENT REPORT OF:

WATER SHUT OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☒ ABANDONMENT* ☒
(Other)

(Note: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. REPORT ON WORK OR COMPLETION OPERATIONS (Refer to space 16 pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is functionally drilled, give subsurface location and measured and true vertical depths for all markers and zones pertinent to this work.)

- 5-30-89 Pulled 2 3/8" tubing & 5 1/2" Guberson Packer out of hole.
Set 5 1/2" Halliburton Bridge Plug at 10,000' with 40' cement on top.
Perforate 7 squeeze holes at 8,003'.
- 5-31-89 Cement 5 1/2" casing with 375 sacks Halliburton 50/50 Poz mix cement. Plug back total depth to 7,836'.
- 6-02-89 Perforate well, 2 shots per foot: 7,536', 7,548', 7,552', 7,557', 7570', 7,577', 7,589', 7,591', 7,615', 7,621', 7,633', 7,641', 7,651', Total of 26 holes.
Acidize well with 4,000 gallons of 15% Nefe Acid, well flowing acid.
- 6-3 &
4-89 Swab test well. Acid water, Gas, and trace of oil.
- 6-6-89 Sand Frac well with 100,000 gallons Halliburton Versagel. Carrying 200,000 lbs of 16-30 Ottawa Sand. Well shut in - 1,900 lb 5 1/2" casing.
- 6-7-89 Well Flowing Frac water on 24/64" choke - total of 368 bbls.
- 6-8-89 Ran total of 7,485' of 2 3/8" tubing in hole.

(Continued on page 2)

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE President DATE June 26, 1989

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side