## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

ERGY AND MINERALS DE	MAH	INIE
	7	
DISTRIBUTION		
SANTA PE	1	<u> </u>
FILE	L	1
U.S.O.S.		↓
LAND OFFICE	<del> </del>	↓
OPERATOR	11	1

## OIL CONSERVATION DIVISION

Form C-103

DISTRIBUTION	Р. О. ВО	X 2088	Revised 10-1-78
		V MEXICO 87501	
SANTA PE	SANTA FE, NEV	A MEVICO OLDO	Sa. Indicate Type of Lease
rue iv			State K Fee
U.S.O.S.	İ		5. State Oli 6 Gas Lease No.
LAND OFFICE			L 1607
OPERATOR /	ĺ		THE TOO I
SUNDR'	Y NOTICES AND REPORTS OF	N WELLS	
(DO NOT USE THIS FORE FOR PROJ	POSALS TO CRILL OF TO DEEPEN OR PLUG TON FOR PERMIT - " FORM C-1611 FOR SI	DELVED	7. Unit Agreement Name
535 - 100000		K = -	
CAE TY			8. Farm or Lease Name
WELL WELL	OTHER.	OCT 9 1979	g, Farm of Education
Name of Operator		<b>00</b> . •	New Mexico State "AA"
Anadarko Production	n Company		9. Well No.
August 100	24 -4 997	55 D. C. G.	1
Address of Operator	Hills, New Mexico 882	ARTESIA, OFFICE	10. Field and Pool, or Wildcat
			in a mark Morre
Location of Well	37A	th LINE AND 1980 FEET FR	North Turkey Track Morr
*	1980 FEET FROM THE NOTE	II LINE AND	
UNIT LETTER		005	
_	ION	L8S RANGE Z8E NM	· (
THE West LINE, SECTI	IONTOWNSHIP		Million Holding
	15. Elevation (Show wheth	her DF, RT, GR, etc.)	12. County
	12. Fleaduou (pues and	2401 E CT	Eddy
		3481.5 GL	Orlean Data
Marian	Appropriate Box To Indicate	Nature of Notice, Report or SUBSEQUE	Other Data
6. Check	Appropriate box to married	subseque	ENT REPORT OF:
NOTICE OF I	INTENTION TO:		_
	·	$\neg I$	ALTERING CARING
	PLUG AND ABANDON	REMEDIAL WORK	PLUG AND ADANDONMENT
		COMMENCE DESLLING OPHS.	. 22.
i I	ANALES BLANE	CASING TEST AND CEMENT JOB	Treat
i I		Fracture	1 TEST
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OK ALTER CABING	CHARGE TARRED		
i I	CHARGE PAGE		
TEMPORARILY ABANDON PULL ON ALTER CABING	ſ		
TEMPORARILY ABANDON PULL ON ALTER CABING	ſ		
TEMPORARILY ABANDON PULL OK ALTER CASING	ſ		
OTHER	ſ		uding estimated date of starting any propos
TEMPORARILY ABANDON PULL ON ALTER CABING	ſ		
i I	CHANGE PLANS	CASING TEST AND CEMENT JOB	Treat

- 1. Rigged up pulling unit.
- 2. Fracture treated Morrow perforations 10,794 10,806 & 10,816 10,821 with 772 barrels of 3% HCL Ese Frac, 30,000# 20/40 sand, 19,000# 100 mesh sand & 1,064,575 SCF of CO2. Average frac rate = 10.2 BPM @ 9200#.
- 3. Flowed well down and returned to Sales Line.

		•	
•		•	
18. I hereby certify that the information above is true and com	plete to the best of my know	viedge and belief.	
18. I hereby certify that the manual			
Original Signed by		Supervisor	DATE October 4, 1979
Original Signed by  Jerry E. Buckles	TITLE ATER		OCT 1 0 1979