Harvey E. Yates Company Travis Deep Unit #4 Page 2

### 8. ANCILLARY FACILITIES:

A. None required.

### 9. WELLSITE LAYOUT:

- A. Exhibit C shows the relative location and dimensions of the well pad, reserve pits and major rig components. The pad will be rotated and have the pits on the south and the V door on the west due to the fact that the afore mentioned pipeline is on the north edge of the location.
- B. The terrain is fairly flat and the topsoil consists of sandy soil and rock.
- C. There will be 4' cut on the south side of the pad.
- D. The pad and pit area have been staked.

#### 10. PLANS FOR RESTORATION OF THE SURFACE:

- A. After finishing drilling and/or other completion operations, all equipment and other material not needed for further operations will be removed. Pits will be filled and the location cleaned of all trash and junk to leave the wellsite as pleasant in appearance as possible.
- B. If the proposed well in non-productive, all restoration and/or vegetation requirements of the Bureau of Land Management and the United States Geological Survey will be complied with and will be accomplished as quickly as possible. All pits will be filled and leveled within 90 days after abandonment.

# 11. OTHER INFORMATION:

- A. The surface is privately owned by Bogle Farms and we have written to advise them of our plans.
- B. The topography consists of relatively flat land with broomweed, mesquite and cacti. The usual inhabitants of this area are rodents, reptiles, coyotes, etc.
- C. There is a stock watering tank approximately 1/2 mile west of our proposed drillsite. No lakes, streams or rivers are in the immediate area.
- D. There are no occupied dwellings or windmills in the area of the wellsite, but there is a house about 1 mile east of this location.
- E. A powerline runs from east to west approximately 1/2 mile south of the location.
- F. There is no evidence of any archaeological, historical or cultural sites in the area.

# 12. OPERATOR'S REPRESENTATIVES:

Peck Hardee Harvey E. Yates Company 300 Security Bank Building Roswell, New Mexico 88201 Office: 505/623-6601 Mobile: 505/623-0989 #4114 Home: 505/623-8980 Fred G. Yates Harvey E. Yates Company 300 Security Bank Building Roswell, New Mexico 88201 Office: 505/623-6601 Mobile: 505/623-0989 #4109 Home: 505/622-5387