30-015-22709

OGRID # 10179

PROP # 12989

Pool # 76400

.

2-14-79 Sual Sateralog marso 134 2913 - 11140' Comp. Mentron Farm. Dena 0. 11140'

2

IT IS THEREFORE ORDERED: Case = 6317 9-13-78 R.J.S. order R. 5808

(1) That a 301.75-acre non-standard gas proration unit

In the South Empire-Morrow Gas Pool comprising the N/2 of Section 18, Township 18 South, Range 29 East, NMPM, Eddy County, New Mexico, is hereby established and dedicated to a well to be drilled at an unorthodox location, hereby approved, 1980 feet from the North line and 660 feet from the East line of said Section 18.

~

NC TOPS PER LLB PENN- 8980 STELLN- 9746 ATOKA - 10231 MORIS - 10610 MORICI - 10708



. . . .

		•		Dil Cons.	
Form 3160-5	UNITE	ATES	<b>N.</b> N.	JIV-DIST. 2	215
JUNE 1990)	DEPARTMENT OF T		1301 W.	Grand Avenue	017
	BUREAU OF LANI	D MANAGEMENT	Artesia	a, NM <sup>****</sup> 88210	
	SUNDRY NOTICES AND	REPORTS ON WELLS	5. Le	asé Designation and Serial No. NM-23417	
Do not use thi		to deepen or reentry to a differe	nt reservoir. 6. If I	Indian, Allottee or Tribe Name	
	Use "APPLICATION FOR PI	ERMIT" for such proposals			
	SUBMIT ORIGIN	IAL + 6 COPIES	7. 11	Unit or CA, Agreement Designation	
		21232	93037 8. We	ell Name and No.	
	Oil X Gas Well Well	Other 22		Travis Deep Unit #4	_
Name of Operator			NECSA S	30-015-2270	9
Address and Telephone No	0.	13 At	SPL CO	field and Pool, or Exploratory Area	
P.O. Box 1933, R		<u> </u>	2 3	Empire Morrow, South	
. Location of Well (Footage Jnit H. 1,980' FN	e, Sec., T., R., M., or Survey Description)		1.0/	County or Parish, State	
Sec 18, T18S, R2		× 4191	91.71 213	Eddy County, NM	
		(s) TO INDICATE NATURE	OF NOTICE, REPO		
TYPE OF SI			TYPE OF ACTIO		
		Abandonment		1	_
	Notice of Intent		L	Change of Plans	
r1	Subsequent Provid	Recompletion	L	New Construction	
	Subsequent Report	Plugging Back	L	Non-Routine Fracturing	
<b>v</b> -1		Casing Repair		Water Shut-Off	
<u>^</u>	Final Abandonment Notice	Altering Casing		Conversion to Injection	
•		Other			
give subsurface locations	and measured and true vertical depths for all Smith & Marrs.				
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH w/5 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol t 4 1/2'' csg @ 6,600'. POG I w/tbg to 6,656' & spot 35 ot 35 sxs plug @ 4,756'. V	nt details, and give pertinent dates, including es	. GIH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490	(Note: Report results of multiple completion on W Completion or Recompletion Report and log form) sed work. If wells directionally drilled, 9,300'	
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH w/5 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol t 4 1/2'' csg @ 6,600'. POG I w/tbg to 6,656' & spot 35 ot 35 sxs plug @ 4,756'. V OC & tag plug @ 2,622'.	nt details, and give pertinent dates, including en markers and zones pertinent to this work.)* c on top of CIBP @ 10,740'. de w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs	. GIH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,49 Spot 100 sxs plug @	<ul> <li>(Note: Report results of multiple completion on W Completion or Recompletion Report and log form) sed work. If wells directionally drilled,</li> <li>9,300'</li> <li>0'.</li> <li>2,976'.</li> </ul>	
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH w/5 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol t 4 1/2" csg @ 6,600'. PO( I w/tbg to 6,656' & spot 35 of 35 sxs plug @ 4,756'. V 0C & tag plug @ 2,622'. t & pull 450' 8 5/8" csg. G I & tag plug @ 399'. Pum	nt details, and give pertinent dates, including en markers and zones pertinent to this work.)* c on top of CIBP @ 10,740'. ie w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. cill w/tbg to 509' & spot 11: p additional 35 sxs cmt pl	. GIH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug.	(Note: Report results of multiple completion on W         Completion or Recompletion Report and log form)         sed work. If wells directionally drilled.         9,300'         0'.         @ 2,976'.	
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH 335	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol 4 1/2'' csg @ 6,600'. POO I w/tbg to 6,656' & spot 35 ot 35 sxs plug @ 4,756'. V OC & tag plug @ 2,622'. I & pull 450' 8 5/8'' csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @	ant details, and give pertinent dates, including en markers and zones pertinent to this work.)* c on top of CIBP @ 10,740'. de w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. details w/tbg to 509' & spot 111 p additional 35 sxs cmt plug. g 95'.	GIH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. 1 Install dry bole ma	(Note: Report results of multiple completion on W         Completion or Recompletion Report and log form)         sed work. If wells directionally drilled.         9,300'         0'.         @ 2,976'.         Tag plug @	VED
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol 4 1/2'' csg @ 6,600'. POO I w/tbg to 6,656' & spot 35 ot 35 sxs plug @ 4,756'. V OC & tag plug @ 2,622'. I & pull 450' 8 5/8'' csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @	ant details, and give pertinent dates, including en markers and zones pertinent to this work.)* c on top of CIBP @ 10,740'. de w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. dill w/tbg to 509' & spot 111 p additional 35 sxs cmt pl @ 95'. of 5 sxs surface cmt plug.	GIH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. 1 Install dry hole ma	(Note: Report results of multiple completion on W         Completion or Recompletion Report and log form)         sed work. If wells directionally drilled.         9,300'         0'.         @ 2,976'.         Tag plug @	
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol 4 1/2'' csg @ 6,600'. PO( I w/tbg to 6,656' & spot 35 ot 35 sxs plug @ 4,756'. V 0C & tag plug @ 2,622'. I & pull 450' 8 5/8'' csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @ I & tag plug @ 91'. Pump	ant details, and give pertinent dates, including en markers and zones pertinent to this work.)* c on top of CIBP @ 10,740'. c w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. c Tag plug @ 509' & spot 11: c Approved as to plugain c Liability as to plugain	GIH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. 1 Install dry hole ma	(Note: Report results of multiple completion on W         Completion or Recompletion Report and log form)         sed work. If wells directionally drilled.         9,300'         0'.         2,976'.         Fag plug @         Irker. P&A	VED
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH com	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol 4 4 1/2" csg @ 6,600'. POG I w/tbg to 6,656' & spot 35 ot 35 sxs plug @ 4,756'. V 0C & tag plug @ 2,622'. I & pull 450' 8 5/8" csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @ I & tag plug @ 91'. Pump nplete.	nt details, and give pertinent dates, including en markers and zones pertinent to this work.)* c on top of CIBP @ 10,740'. e w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. c WOC. Tag plug @ 4,408'. c HH w/tbg to 509' & spot 11: p additional 35 sxs cmt pl @ 95'.	GIH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. 1 Install dry hole ma	(Note: Report results of multiple completion on W         Completion or Recompletion Report and log form)         sed work. If wells directionally drilled.         0'.         2,976'.         Tag plug @         Irker. P&A         FEB         LES BABY	VED
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH w/5 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH con	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol t 4 1/2" csg @ 6,600'. PO( I w/tbg to 6,656' & spot 35 of 35 sxs plug @ 4,756'. V 0C & tag plug @ 2,622'. t & pull 450' 8 5/8" csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @ I & tag plug @ 91'. Pump nplete.	nt details, and give pertinent dates, including er markers and zones pertinent to this work.)* To on top of CIBP @ 10,740'. The w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. Tag plug @ 4,4	GiH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. T Install dry hole ma <sup>g of the well bore</sup> .	(Note: Report results of multiple completion on W         Completion or Recompletion Report and log form)         sed work. If wells directionally drilled.         0'.         @ 9,300'         0'.         @ 2,976'.         Fag plug @         Irker. P&A         FEB 2 1         LES BABY         PETROLEUM ER	VED
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH com	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol t 4 1/2" csg @ 6,600'. PO( I w/tbg to 6,656' & spot 35 of 35 sxs plug @ 4,756'. V 0C & tag plug @ 2,622'. t & pull 450' 8 5/8" csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @ I & tag plug @ 91'. Pump nplete.	nt details, and give pertinent dates, including en markers and zones pertinent to this work.)* c on top of CIBP @ 10,740'. c w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. c additional 35 sxs cmt plug. p additional 35 sxs cmt plug. f 5 sxs surface cmt plug. Approved as to pluggin, Liability under bond is prestoration is p	GIH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. 1 Install dry hole ma	(Note: Report results of multiple completion on W         Completion or Recompletion Report and log form)         sed work. If wells directionally drilled.         0'.         @ 9,300'         0'.         @ 2,976'.         Fag plug @         Irker. P&A         FEB 2 1         LES BABY         PETROLEUM ER	VED
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH w/5 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spo WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH cont	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol t 4 1/2" csg @ 6,600'. POO I w/tbg to 6,656' & spot 35 of 35 sxs plug @ 4,756'. V OC & tag plug @ 2,622'. t & pull 450' 8 5/8" csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @ I & tag plug @ 91'. Pump nplete.	nt details, and give pertinent dates, including er markers and zones pertinent to this work.)* To on top of CIBP @ 10,740'. The w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. Tag plug @ 4,4	GiH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. T Install dry hole ma <sup>g of the well bore</sup> .	(Note: Report results of multiple completion on W         Completion or Recompletion Report and log form)         sed work. If wells directionally drilled.         0'.         @ 9,300'         0'.         @ 2,976'.         Fag plug @         Irker. P&A         FEB 2 1         LES BABY         PETROLEUM ER	VED
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH w/5 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spo WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH cont	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol t 4 1/2" csg @ 6,600'. POO I w/tbg to 6,656' & spot 35 of 35 sxs plug @ 4,756'. V OC & tag plug @ 2,622'. t & pull 450' 8 5/8" csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @ I & tag plug @ 91'. Pump nplete.	nt details, and give pertinent dates, including er markers and zones pertinent to this work.)* To on top of CIBP @ 10,740'. The w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. Tag plug @ 4,4	GiH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. T Install dry hole ma <sup>g of the well bore</sup> .	(Note: Report results of multiple completion on W         Completion or Recompletion Report and log form)         sed work. If wells directionally drilled.         0'.         @ 9,300'         0'.         @ 2,976'.         Fag plug @         Irker. P&A         FEB 2 1         LES BABY         PETROLEUM ER	VED
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH w/5 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH con	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol 4 4 1/2" csg @ 6,600'. POG I w/tbg to 6,656' & spot 35 ot 35 sxs plug @ 4,756'. V 0C & tag plug @ 2,622'. I & pull 450' 8 5/8" csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @ I & tag plug @ 91'. Pump mplete.	nt details, and give pertinent dates, including er markers and zones pertinent to this work.)* To on top of CIBP @ 10,740'. The w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. Tag plug @ 4,4	GiH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. T Install dry hole ma <sup>g of the well bore</sup> .	(Note: Report results of multiple completion on W         Completion or Recompletion Report and log form)         sed work. If wells directionally drilled.         0'.         @ 9,300'         0'.         @ 2,976'.         Tag plug @         Irker. P&A         FEB         LES BABY         PETROLEUM Er         18-Feb-02	VED
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH w/5 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH con	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol 4 4 1/2" csg @ 6,600'. POG I w/tbg to 6,656' & spot 35 ot 35 sxs plug @ 4,756'. V 0C & tag plug @ 2,622'. I & pull 450' 8 5/8" csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @ I & tag plug @ 91'. Pump mplete.	ant details, and give pertinent dates, including en markers and zones pertinent to this work.)* The w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,4	GiH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. T Install dry hole ma g of the well bore.	(Note: Report results of multiple completion on W         Completion or Recompletion Report and log form)         sed work. If wells directionally drilled.         0'.         @ 9,300'         0'.         @ 2,976'.         Tag plug @         Irker. P&A         FEB         LES BABY         PETROLEUM Er         18-Feb-02	VED
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH w/5 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH con 14. I hereby certify that Signed (This space for Federal Approved by Conditions of approve	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol 4 4 1/2" csg @ 6,600'. POG I w/tbg to 6,656' & spot 35 ot 35 sxs plug @ 4,756'. V 0C & tag plug @ 2,622'. I & pull 450' 8 5/8" csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @ I & tag plug @ 91'. Pump mplete.	nt details, and give pertinent dates, including en markers and zones pertinent to this work.)* To n top of CIBP @ 10,740'. The w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. Tag plug @	GiH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. T Install dry hole ma g of the well bore.	(Note: Report results of multiple completion or Necompletion Report and log form)         Completion or Recompletion Report and log form)         Sed work. If wells directionally drilled.         0'.         @ 9,300'         0'.         @ 2,976'.         Tag plug @         Irker. P&A         FEB 2 1         LES BABY         PETROLEUM Er         18-Feb-02	VED
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH w/5 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH corn 14. I hereby certify that Signed (This space for Feder Approved by Conditions of approve	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol 4 4 1/2" csg @ 6,600'. POG I w/tbg to 6,656' & spot 35 ot 35 sxs plug @ 4,756'. V 0C & tag plug @ 2,622'. I & pull 450' 8 5/8" csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @ I & tag plug @ 91'. Pump mplete.	nt details, and give pertinent dates, including en markers and zones pertinent to this work.)* To n top of CIBP @ 10,740'. The w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs WOC. Tag plug @ 4,408'. Tag plug @	GiH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. T Install dry hole ma 8 of the well bore. Tetained untip on Analyst	(Note: Report results of multiple completion or Necompletion Report and log form)         Completion or Recompletion Report and log form)         Sed work. If wells directionally drilled.         0'.         @ 9,300'         0'.         @ 2,976'.         Tag plug @         Irker. P&A         FEB 2 1         LES BABY         PETROLEUM Er         18-Feb-02	VED
give subsurface locations 2/6/02 MI \$ 2/7/02 GIH w/5 2/8/02 GIH 2/11/02 Cut 2/12/02 GIH 2/13/02 Spc WO 2/14/02 Cut 2/15/02 GIH 335 2/16/02 GIH con 14. I hereby certify that Signed (This space for Feder Approved by Conditions of approve Thile 18 t or represe	and measured and true vertical depths for all Smith & Marrs. I w/bailer & dump 35' cmt 0' cmt on top. I w/tbg to 8,316'. Roll hol t 4 1/2" csg @ 6,600'. POO I w/tbg to 6,656' & spot 35 ot 35 sxs plug @ 4,756'. V OC & tag plug @ 2,622'. t & pull 450' 8 5/8" csg. G I & tag plug @ 399'. Pum 5'. Spot 20 sxs cmt plug @ I & tag plug @ 91'. Pump mplete.	nt details, and give pertinent dates, including er markers and zones pertinent to this work.)* c on top of CIBP @ 10,740'. ie w/9# mud. Spot 25 sxs of OH & lay down 183 jts 4 1/. 5 sxs cmt plug. WOC 4 hrs VOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. WOC. Tag plug @ 4,408'. H w/tbg to 509' & spot 114 p additional 35 sxs cmt pl g 95'. 75 sxs surface cmt plug. Autroved as to pluggin, autrace restoration is a CCC Title Production Title	GiH @ set CIBP @ cmt plug @ 8,316'. 2" csg. s. Tag plug @ 6,490 Spot 100 sxs plug @ 5 sxs cmt plug. ug @ 399'. WOC. T Install dry hole ma 8 of the well bore. Tetained untip on Analyst	(Note: Report results of multiple completion or Necompletion Report and log form)         Completion or Recompletion Report and log form)         Sed work. If wells directionally drilled.         0'.         @ 9,300'         0'.         @ 2,976'.         Tag plug @         Irker. P&A         FEB 2 1         LES BABY         PETROLEUM Er         18-Feb-02	VED

3003 EEB 1 8 WH 8: 00 RECEIVED

BUREAD OF LAND MEML