

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

MAY 19 1992

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Hondo Drilling Company

3. Address and Telephone No.

P.O. Drawer 2516 - Midland, Texas 79702-2516 (915)682-9401

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980 FNL 1980 FEL Unit G
Sec.30, T-18-5, R-29-E

5. Lease Designation and Serial No.

N.M. 56426

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Sivley - Federal #2

9. API Well No.

30-0152277000

10. Field and Pool, or Exploratory Area

E. Palmillo Bone Springs

11. County or Parish, State

Eddy - New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) Set 5 1/2 CIBP at 6500' cap W/ 14 sacks cement
- 2) Load hole W/mud
- 3) Cut and pull 5 1/2 casing at 4465'
- 4) Spot 35 sacks of cement plug at 4540' W.O.C. tag at 4384'
- 5) Spot 45 sacks of cement plug at 3019' W.O.C. tag at 2822'
- 6) Spot 60 sacks of cement plug at 2409' W.O.C. tag at 2213'
- 7) Spot 30 sacks of cement plug at 400'
- 8) Spot 14 sacks of cement plug at surface and set up P.A. marker

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

Regina M. Thompson

Title

Supervisor

Date

2-28-92

(This space for Federal or State office use)

Approved by

David H. Glass

Title

Date

5-15-92

Conditions of approval, if any: