Form 3160-5 (August 1999)

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

N.M. Oil Co. Division

811 S. 1st Street FORM APPROVED **UNITED STATES** OMB No. 1004-0135 Expires November 30, 2000 DEPARTMENT OF THE INTERIOR Artesia, NM 882110 **BUREAU OF LAND MANAGEMENT** SUNDRY NOTICES AND REPORTS ON WELLS NM-27276 Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 6. If Indian, Allottee or Tribe Name If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse sign 1. Type of Well Oil Well A Gas Well Other 8. Well Name and No. Name of Operator Benson Deep Unit #1 Yates Petroleum Corporation 9. API Well No. 3a. Address 3b. Phone No. (include area code) 30-015-22793 105 S. 4th St. - Artesia, NM 88210 505-748-1471 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Undesignated Strawn 660' FSL & 2180' FEL of Section 33-T18S-R30E (Unit O, SWSE) 11. County or Parish, State Eddy Co., NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Water Shut-Off ☐ Acidize ☐ Deepen Production (Start/Resume) Notice of Intent Well Integrity Alter Casing Fracture Treat ■ Reclamation Casing Repair New Construction ☐ Recomplete Other Abandon Morrow ■ Subsequent Report Change Plans ☐ Plug and Abandon & return to Strawn Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Propose to abandon perforations 11538-11615' (Morrow) and return well to Strawn as follows: 1. Load tubing and casing with 2% KCL water. Pressure test annulus to 1000 psi. Nipple down tree and nipple up BOP. Unset packer at 11447'. TOOH with packer. 2. Wireline set a CIBP at 11500'. Cap CIBP with 35' of cement to abandon perforations 11538-11615'. NOTE: There is a CIBP at 11760' with 35' of cement on top to abandon perforations 11794-11803' (Morrow). 4. Perforate 10646-10711' (Strawn), acidize as necessary. NOTE: Perforations  $\sqrt{B}$ 10648-10718' (Strawn) are open and will also be acidized. Swab/flow test. Place well into production. If 150 mcfpd cannot be restored out of Strawn perforations, will recomplete to Wolfcamp as follows: Load tubing. Nipple down tree and nipple up BOP. POOH with tubing and packer. 14. I hereby certify that the foregoing is true and correct CONTINUED ON NEXT PAGE: Name (Printed/Typed) Title Operations Technician Rusty Klei Signature Date June 30, 2000 THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title

W. Salah

ROSWELL, NM JUL 05 2000 JUL 05 2000

YATES PETROLEUM CORPORATION Benson Deep Unit #1 Section 33-T18S-R30E Eddy County, New Mexico

## SUNDRY NOTICE CONTINUED:

- 2. Perforate 9902-9912' (Wolfcamp), acidize as necessary for production.
- 3. Swab/flow test.
- 4. Place well into production.

If decision is made to commingle Strawn and Wolfcamp production, application will be made to BLM and OCD.

Operations Technician

June 30, 2000