

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-015-22807

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-7244-30

Lease Name or Unit Agreement Name
Empire Abo Unit K

8. Well No.
131

9. Pool name or Wildcat
Empire Abo

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3517' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator ☒
ARCO Permian

3. Address of Operator
P.O. Box 1089 Eunice, NM 88231

4. Well Location
Unit Letter **L** **1500** Feet From The **S** Line and **600** Feet From The **W** Line
Section **2** Township **18S** Range **27E** NMPM **Eddy** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3517' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

OTHER: **Squeeze old perfs & re-perf**

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6145' PBD: 6140' PERFS: 6014-6034'

12/31/97: RIH w/workstring. Unset pkr. POH w/bad tbg & workstring.
01/05/98: RIH w/5-1/2" bit & scrapper. Ran to 6031'. POH w/bit, scrapper & tbg.
RIH w/pkr & RBP. Set RBP @ 5744'. Set PKR @ 5716'. Test to 600 # psi
load backside & test to 500# psi. Held good. Release PKR & RBP.
01/06/98: RIH w/5-1/2" CR to 5994'. Pmp 25 bbls.
01/07/98: Squeeze old perfs w/100 sx Class "C" neat. Reverse 50 sx to pit.
01/08/98: RIH w/tbg & CIBP set @ 5754'. Test CIBP to 600#. tested good. RIH w/5-1/2"
lockset pkr. Set w/176 jts tbg @ 5491'. Perf 5710-5530'
01/12/98: Acidize perfs w/3000 gals 15% NEFE Nitrofield acid. RIH w/2-3/8" J-55 tbg
set @ 5562'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Assistant DATE 03/25/99
TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 4-6-99