

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

dst
Op

OIL CONSERVATION DIVISION

DISTRICT I

P. O. Box 1980 Hobbs, NM 88240

P. O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II

P. O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd, Aztec, NM 87410

Well API NO.

30-015-22830

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

E-1392

7. Lease name or Unit Agreement Name

TRAVIS STATE

8. Well No.

1

9. Pool name or Wildcat

UNDESG. BONE SPRING

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

OIL

☒

GAS

☐

WELL

WELL

OTHER

2. Name of Operator

Harvey E. Yates Company

3. Address of Operator

P.O. Box 1993, Roswell, NM 88202 1-505-623-6601

4. Well Location

Unit Letter

K

:

1,780 Feet From The

SOUTH

Line an

2,080

Feet From The WEST

Line

Section

13

Township

18S

Range 28E


NMPM

EDDY

County



10. Elevation (Show whether DE, RKB, RT, GR, etc.)
3585' GL



11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

☐

PLUG AND ABANDON

☐

TEMPORARILY ABANDON

☐

CHANGE PLANS

☐

PULL OR ALTER CASING

☐

OTHER:

☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK

☒

ALTERING CASING

☐

COMMENCE DRILLING OPNS.

☐

PLUG AND ABANDONMENT

☐

CASING TEST AND CEMENT JOB

☒

OTHER: TESTING CASING & CMTG. ALONG w/ PERF, ACID & FRAC.

☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

2-1-96 SET CIBP @ 9790'. TEST CSG FROM 6500' TO SURFACE HELD OK. TEST CSG
BELOW 6500' DOWN TO 9790'. HELD OK. RAN CBL FROM 7620 TO 2475' TOC.

2-5-96 MADE 2 DUMP RUNS & DUMP 35' CMT ON CIBP @ 9790'. GHI w/ 5 1/2" CIBP & SET
@ 8260'. MADE 2 DUMP RUNS & DUMP 35' CMT ON CIBP @ 8260'. GHI w/ 4" SQZ GUN &
SHOOT 4 SQZ PERFS @ 7300'. GHI & SET 5 1/2" CMT RET @ 7228'. GHI & SHOOT 4 SQZ
PERFS @ 5490'.

2-6-96 CMT BACKSIDE w/ 700 SXS CL "H" w/ . 6% HALAD 322 & 5# SALT/ SK. REV OUT ALL BUT 8
BBLs CMT LEFT ON RET. (APPROX 336' OF CMT). SPOT 80 SKS @ 5520' & ATTEMPT TO SQZ
OFF UPPER PERFS @ 5490. UNABLE TO GET SQZ.

2-7-96 DRL OUT CMT & TEST SQZ PERFS. DID NOT HOLD.

2-8-96 CONT DRLG TO 6840 (TAG HARD CMT) DRL OUT TO 6862'. NEW PBTD.

2-10-96 SET 5 1/2" HOWCO EASY DRL RET @ 5426'. SQZ w/ 150 SKS CL C w/ . 3% HALAD 9. DRL OUT.

2-14-96 PERF BS 6202-6494 (OA). ACIDIZE w/ 3000 GALS 15% NEPE & BS.

2-19-96 FRAC PERF w/ 50360 GALS X-LINK & 120k# SAND.

2-23-96 PUT ON PROD. SN @ 6595' TAC @ 5880'. TURN OVER TO PUMPER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Ray F. Nokes

TITLE

PROD. MGR. / ENGINEER.

Date

2/27/96

TYPE OR PRINT NAME

RAY F. NOKES

TELEPHONE NO.

1-505-623-6601

(This space for State use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

Approved by

Title

Date

MAR 5 1996

Conditions of approval, if any: