
Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department



O	T	T. (C	O	N	S	EF	7 5	I	ГΖ	ГТ	O	N	Γ	T	V	19	ST	O	N
v	ъ.	L	•	\smile	Τ.4			• 1	, ,	7 1	··	v	T.4			v	T.	Jl	v	7.7

DISTRICT I OIL CONSERVATION	ON DIVISION
P.O. Box 1980, Hobbs NM 88241-1980 2040 Pached	CO St. WELL API NO.
DISTRICT II Santa Fe, NM P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE 6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON W	ELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPE DIFFERENT RESERVOIR. USE "APPLICATION FOR PI (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL GAS WELL OTHER OTHER	
2. Name of Operator	8. Well No.
BP America Production Company	L-155
3. Address of Operator P.O. Box 1089 Eunice, NM 88231	9. Pool name or Wildcat EMPIRE ABO
4. Well Location	Line and 2025 Feet From The E Line
Unit Letter 0: 1040 Feet From The S	Line andE Line
Check Appropriate Box to Indicate NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS PULL OR ALTER CASING OTHER: Workover	te Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:
MIRUPU. NDWH. NUBOP. Drop SV and set in SN @ 5987'. POH Chemically cut tbg above pkr. GIH w/overshot to top of fish. Swab well down to SN. Kill well if necessary. Carrier w/2 JSPF 5790-5918'. PPI perfs w/50 gals/ft. 15% HCL NEFE. RIH w/production assy. NDBOP. NUWH. Swab for test., Return well to production.	tch fish.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Sr. Administrative Assistant

TYPE OR PRINT NAME Kellie D

TELEPHONE NO. 505.394.1649

DATE TTTLE APPROVED BY_ CONDITIONS OF APPROVAL, IF ANY: