

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

CISF  
Dpt

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

12-11-91

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO.
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Sol West III		6. State Oil & Gas Lease No. E - 1286
3. Address of Operator P.O. Box 10151, El Paso, Texas 79992		7. Lease Name or Unit Agreement Name Turkey Trac Com
4. Well Location Unit Letter <u>I</u> : <u>660</u> Feet From The <u>East</u> Line and <u>1980</u> Feet From The <u>South</u> Line Section <u>26</u> Township <u>18-S</u> Range <u>28-E</u> NMPM <u>Eddy</u> County		8. Well No. <u>1</u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3459.4 GL		9. Pool name or Wildcat Undesignated G8-SA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-11-91

Plugging operations began. Ran and set Howco E-Z drill CIBP at 2150' K.B., tag same. Mixed and pumped 135 barrels mud laden fluid and 12 sacks cement. Plug No. 1 from 2150' - 2110' (40' plug). Tag CIBP at 2150', no cement fill above CIBP. Went in hole and set Howco E-Z drill CIBP at 2135'. Mix and spot Plug No. 2 from 2135' - 2095' (40') 12 sacks class "C" cement. Mix and spot Plug No. 3 from 1780' - 1680' (100') with 30 sacks class "C" cement. Mix and spot Plug No. 4 from 650' - 400' (250') from 65 sacks class "C" cement. Mix and spot Plug No. 5 from 45' to surface (30') with 16 sacks class "C" cement. Weld on dry hole marker.

Post ID-2  
1-10-92  
P4A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>James F. O'Briant</u>	TITLE <u>Agent for Sol West III</u>	DATE <u>1/17/92</u>
TYPE OR PRINT NAME <u>James F. O'Briant</u>	TELEPHONE NO. <u>915-683-5511</u>	

(This space for State Use)

APPROVED BY James F. O'Briant TITLE Agent for Sol West III DATE 1-2-92

CONDITIONS OF APPROVAL, IF ANY: