Submit 3 Copies

## State of New Mexico Energy Minerals and Natural Resources Department

Form C-103

to Appropriate District Office	Elicity, Willicials and Watera	1 1105001000 Dopurtinoit	Keybeu 1-1-09
DISTRICT I	OIL CONSERVAT	ION DIVISION	
P.O. Box 1980, Hobbs NM 88241-1980		_	WBLL API NO. 30-015-22986
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NA	co St. 1 875056 7 8 9 7077	5. Indicate Type of Lease  STATE X FEE
DISTRICT III		· A PS	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410	······································	1.05 tog \$	L-3853
SUNDRY NOT	ICES AND REPORTS ON WI	= LA SICUEIVED TO A TO	
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESEI (FORM C	PPOSALS TO DRILL OR TO DEEP RVOIR. USE "APPLICATION FOR F -101) FOR SUCH PROPOSALS.)	ERMIT"	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL WELL X	OTHER	)	NEW MEXICO STATE 'AB' COM
2. Name of Operator			8. Well No.
Anadarko Petroleum Corp.			1
3. Address of Operator	70702		9. Pool name or Wildcat TURKEY TRACK MORROW N. (GAS)
P.O. Box 2497 Midland, TX  4. Well Location	13/04		
4. Well Location Unit Letter H 198	) Feet From The NORTI	Line and 66	Feet From The EAST Line
		005	ENNV _
Section 36	Township 18S	Range 28E ether DF, RKB, RT, GR, etc	NMPM EDDY County
X/////////////////////////////////////	10. Elevation (Snow WI	3409.5' GR	<u> </u>
Chook At	propriate Box to Indica		Report, or Other Data
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:			
NOTICE OF II	41ENTION 10.	_	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. U PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB
OTHER:		OTHER:	
			A land the state of the state o
12. Describe Proposed or Completed Op	erations (Clearly state all pertinen	t details, and give pertinent da	ates, including estimated date of starting any proposed
work) SEE RULE 1103.			
1. RUPU. KILL WELL W/LEASE CONDENSATE. INSTALL BOP.			
2. TOH W/TBG & PACKER. ISOLATE MORROW PERFS (10,962- 10,994') WITH RETRIEVABLE BRIDGE PLUG.			
3. REPERFORATE UPPER MORROW INTERVAL (10,837-10,861').			
4. TIH W/TBG & PACKER.			
5. STIMULATE UPPER MORROW.			
<ol> <li>PUT WELL DOWN GAS SALES LINE. RDPU.</li> <li>WHEN THE UPPER ZONE PRESSURE DECLINES, THE ZONES WILL BE COMMINGLED BY RETRIEVING BRIDGE PLUG.</li> </ol>			
/. WHEN THE UPPER ZUNE	FREJUNE DEGLINES, THE E	0,,20 ,,222 02 00,,2,14	
•			
I hereby certify that the information above i	s true and complete to the best of my kno	wledge and belief.	
SIGNATURE Richard hand	udole	TITLE PRODUCTION ENG	DATE 08/04/99
TYPE OR PRINT NAME RICHARD LAU	DERDALE		TELEPHONE NO. 915/683-0559
(This space for State Use)	Line W. l.	District :	Trade made)
ADDROLUTA DV	Sim W. Sugar	TITLE	DATE 8-11-99
APPROVET) BY			

APPROVED BY\_