

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

RECEIVED  
NEW MEXICO OIL CONSERVATION COMMISSION

OCT 24 1980

O. C. D.  
ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 41	
7. Unit Agreement Name	
8. Farm or Lease Name	
Amoco-McKay State	
9. Well No.	
#1	
10. Field and Pool, or Wildcat	
Undesign. ABO	
12. County	
Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator  
PETROLEUM DEVELOPMENT CORPORATION

3. Address of Operator  
9720-B Candelaria, N.E., Albuquerque, N. M., 87112

4. Location of Well  
UNIT LETTER I, 760 FEET FROM THE east LINE AND 1980 FEET FROM THE south LINE, SECTION 25 TOWNSHIP 18S RANGE 21E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
4099 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Plug and abandon</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, including estimated date of starting any proposed work) SEE RULE 1103.

1. Cut 4 1/2" casing @ 3,400'.

2. Spot following cement plugs:  
ABO 35 sx - 3,450' - 3,350' + Tag  
int 50 sx - 1,850' - 1,750' + Tag  
sur. 35 sx - 435' - 335'  
10 sx - At surface  
Install dry-hole marker

5/10/82 STUB AT 3368' could not get in.  
Stub plug fm. 3368 to 3180

5/11/82 Pumped 50 sxs. cl. c w/ .84% CaCl<sub>2</sub> @ 1856  
noc 4hrs. did not tag. opr. thought it was wash out  
pumped 45 sxs. cl. c neat. Tagged next morning @ 1538  
cc: WIO 10/22/80 5/12/82 Pulled tbg. to 448' & pumped 35 sxs. will pump 10 sxs. @ surface &  
Howard Boatwright install P/A mkr.

~~13 3/8 c 383 - Circ~~  
~~8 7/8 c 1800 - Circ~~  
~~4 1/2 c 6209 TOC c 4420' + sized~~  
TOC c 3400  
Perf 4295-4384  
CIBP c 4395  
Perf 5769-714 5820-24  
CIBP c 5750  
CIBP c 3800 w/ 35' cm t  
Perf 3518-28

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Claudia Leslie TITLE Secretary DATE 10/22/80

APPROVED BY W.A. Gressitt TITLE  DATE 10-21-80

CONDITIONS OF APPROVAL, IF ANY:  
Intervals between plugs filled w/ mud

Notify N.M.O.C.C. in sufficient time to witness  
plugging