

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-23025
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Metcalf LT Com
8. Well No. 1
9. Pool name or Wildcat Penasco Draw San Andres Yeso
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3437' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>4M</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1100</u> Feet From The <u>West</u> Line
Section <u>31</u> Township <u>18S</u> Range <u>26E</u> NMPM <u>Eddy</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3437' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-31-9-3-96 - Moved in and rigged up pulling unit. POOH with rods and pump. Shut down for holiday. NOTE: Notified Ray Smith w/OCD-Artesia of commencing operations.
9-4-96 - Nippled up BOP and wellhead. POOH with tubing, seating nipple, perforated sub and mud anchor. TIH with 5-1/2" CIBP on tubing and set CIBP at 2450'. Spotted 60 bbls plugging mud from 2450' to surface. Mixed and pumped 25 sacks Class C cement from 2450-2250' (in 5-1/2" casing). POOH with tubing to 1050'. Mixed and pumped 25 sacks Class C cement from 1050-950' (in 5-1/2" casing). Shut down for night. NOTE: Notified Ray Smith w/OCD-Artesia on cement plugs.
9-5-96 - TIH with tubing and tagged top of cement at 835'. POOH with tubing to 450'. Mixed and pumped 45 sacks Class C cement from 450' to surface. POOH with tubing. Nippled down BOP. Rigged down pulling unit. Cleaned location and installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 9-4-96.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE Sept. 5, 1996

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE 10/24/96

CONDITIONS OF APPROVAL, IF ANY: